



Warranty Services
Work Order
Phone: (905) 848-2069 Fax:(905) 848-2827

Location	Eve - Tower: 1 - Unit: 805 805 - 3515 Kariya
Closing Date	0000
Date	09Jan09
Contact Name(s)	Kamil Ksiazek and Helen North
Contact Telephone#	
Company:	Amacon Service
Attention:	Carlos Bravo
Telephone:	
Fax:	(905) 848-2827
From:	Warranty Services Department - Head Office

Please complete the following items:				
Deficiency Number	Issue		Appointment Date/Time	Notes
7381	FOYER / ENTRY- WALLS-leftside entering - livingroom wall chipped - baseboard	✓		
7382	FOYER / ENTRY- CLOSET-inside bifold closet - left side baseboards needs touchups	✓		
7383	MASTER BEDROOM- WALLS-dent in wall - left side of room 2 ft from outlet	✓		
7384	MASTER BEDROOM- WALLS: 1-right wall by window dent left of outlet - just below	✓		
7385	MASTER BEDROOM- WALLS: 2-leftside of wall top by ensuite bathroom - paint touchups	✓		
7386	MASTER BEDROOM- DOORS-doorframe - top right on entering needs caulking	✓		
7387	MASTER BEDROOM- FLOORING-spots on carpet far left corner	✓		
7388	MASTER BEDROOM- FLOORING: 1-3 spots left of door entering bedroom	✓		
7389	MASTER BEDROOM-ELECTRICAL/LIGHTING-fancoil -- back plate needs to be installed			LISI