

AMACON

LIVE WELL

**Warranty Services
Work Order**

Phone: (905) 848-2069 Fax: (905) 848-2827

Location	Eve - Tower: 1 - Unit: 808 808 - 3515 Kariya
Closing Date	0000
Date	13Feb09
Contact Name(s)	Wai Man Chung
Contact Telephone#	
Company:	Amacon Service
Attention:	Carlos Bravo
Telephone:	
Fax:	(905) 848-2827
From:	Warranty Services Department - Head Office

Please complete the following items:

Deficiency Number	Issue	Appointment Date/Time	Notes
11791	✓ FOYER / ENTRY- WALLS-DRYWALL DENTED left side of closet, see tape	✓	
11793	✓ LIVING/DINING ROOM- FLOORING: 1-quarter round chipped to right of window, see tape	✓	
11795	✓ LIVING/DINING ROOM- ELECTRICAL/LIGHTING-tri-light switch not flush, right of bathroom, see tape	✓	
11796	✓ LIVING/DINING ROOM- ELECTRICAL/LIGHTING: 1-panel missing inside fancoil unit, see tape	X	
11798	✓ LIVING/DINING ROOM- WINDOWS-ALUMINUM dented to left of sliding window, see tapw	X	ALLAN WINDOWS
11799	✓ LIVING/DINING ROOM- WINDOWS: 1-ALUMINUM scratched/marked around balcony door	✓	
11800	✓ LIVING/DINING ROOM- WINDOWS: 2-ALUMINUM THRESHOLD not flush, see tape	✓	
11802	✓ LIVING/DINING ROOM- CEILING-stiple required to right of windows	✓	
11804	✓ LIVING/DINING ROOM- CEILING: 1-stiple scratched in front of windows	✓	
11806	✓ LIVING/DINING ROOM- CEILING: 2-stiple chipped /cracking in front of laundry closet	✓	
11808	✓ LIVING/DINING ROOM- WALLS-wall to right of laundry closet is bowed, see tape	✓	
11810	✓ LIVING/DINING ROOM- WALLS: 1-DRYWALL DENTED right wall below light switch, see tape	✓	
11811	✓ LIVING/DINING ROOM- WALLS: 2-DRYWALL bowed below cable outlet, see tape	✓	
11812	✓ LIVING/DINING ROOM- WALLS: 3-gap in J-mold right side of window, see tape	✓	
11813	✓ MASTER BEDROOM- ELECTRICAL/LIGHTING-paint overspray on electrical panel	✓	
11814	✓ DEN- WALLS-DRYWALL DENTED back wall to right of outlet, see tape	✓	
11815	✓ DEN- CEILING-stiple rough at wall edges	✓	
11818	✓ MAIN BATHROOM- WALLS-install mirror	X	
11819	✓ MAIN BATHROOM- DOORS-lock hardware missing	✓	
11820	✓ MAIN BATHROOM- TUB-silicone around showerhead, tap and faucet, see tape	✓	
11821	✓ MAIN BATHROOM- COUNTERTOPS-chipped above toilet, see tape	X	
11823	✓ MAIN BATHROOM- ELECTRICAL/LIGHTING-GFI plug not flush, see tape	✓	
11824	✓ KITCHEN- FLOORING-quarter round chipped island gable end, see tape	X	KABINETZ
11839	✓ KITCHEN- SINK-SINK STRAINER missing	✓	
11840	✓ KITCHEN- WALLS-bulkhead above microwave chipped, lower right corner	✓	
11841	✓ LAUNDRY CLOSET- DOORS-door doesn't shut properly	✓	

Date Completed: FEB 17 2009

Amacon Customer Care Signature: 

Please schedule your Service Department to complete work on the above Unit. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 848-2827. Failure to comply with this request will give Amacon Developments (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

Back - Forms Menu

ID#

11791/11793/11795/11796/11798/11799/11800/11802/11804/11806/11808/11810/11811/11812/11813/11814/11815/11818/11819/11820/11821/11823/11824/11839/11840/11841
Eve Ph 1 Lot 808