



# WORK ORDER

**№ 28948**

907-Sales File

160 Disco Road, Etobicoke ON P (416) 674-8333 F (416) 674-5399 E [service@lisimechanical.com](mailto:service@lisimechanical.com) 24/7 Pager (416) 612-5474 (LIS

|                    |                                     |                |
|--------------------|-------------------------------------|----------------|
| SOLD TO<br><br>eve | JOB LOCATION<br><br>3515<br>Karinya | DATE CALLED    |
|                    |                                     | CONTACT NAME   |
|                    |                                     | CONTACT PHONE# |

### DESCRIPTION OF WORK

PLEASE PRINT CLEARLY

DESCRIPTION OF WORK  
PLEASE PRINT CLEARLY Unit 907 had leak in Fan Coil unit  
took apart unit found water pooling in Blower Compartment  
indicating leak from above unit Check unit 1007 found  
drain tray overflowing due to blocked drain hose  
Cleared hose and drained out unit no further  
problems

## PARTS & MATERIALS USED

[illegible]

## LABOUR

**I CERTIFY THAT THE ABOVE WORK HAS BEEN SATISFACTORILY COMPLETED**

**TERMS:**  
**NET 30 DAYS**

PLEASE PRINT

**SIGNATURE**