AMACON

un complo pres

LIVE WELL*

AMACON CONSTRUCTION SERVICE REQUEST FORM

NAME:		/ /
· · · · · · · · · · · · · · · · · · ·	chap Wurst	SUITE: 77/2
ΓEL:	ł	BUS. TEL:
CELL: <u>/04</u>	7-408-8317	E-MAIL:
!	QUEST: <u>Nov. 28, 20/0</u>	Permission to enter on scheduled date:
nust be base of the PDI (F oon as a po f your conce	ed on the Tarion Warranty guideli Pre-Delivery Inspection). Your requ ssible. If this is an Emergency plea:	Representative, this form becomes property of Amacon. Your requesines - scratches, nicks, dents are not warrantable, unless noted at timuest will be reviewed and addressed by an Amacon Representative as se contact your concierge immediately at (289) 521-1313 - 24 / hour Element Warranty Guidelines, please see Property Management to 9.
ITEM#	ROOM/LOCATION	DESCRIPTION
/ ×	Washroom	Sold Dane of Garner Missing CARTIEN
20	Washroom	The for Stultub not recieved A
31/	Washroom	Billione servets on tiled floor A.
41	Washrom	Mushroom Your handle has white paint soon
5-1-	Front Jour 1	Trant doc handle has ever paint on it
	7 . 1	
61	Hall way near GoseAL	I duste Sound Missing was left in closet
6 V		
6 V 7 V 8 X	Hall may near bedrein	avarter round missing
6 V 7 V 8 X 9 V	Hall way near bedgeon	Washing Machine Hocks wither when in a
6 V 7 V 8 X 9 V	Hall may near bedrein	avarter round missing washing when in a
6 V 7 V 8 X 9 V	Hall way near bedgeon	Washing Machine Haks wedger when in a was left loose and caved water duringe
6 V 7 V 8 X 9 V	Hall way near bedreim Hall way closet P-trap vale kitchen sink	Washing Machine Haks wedger when in a was left loose and caused water duringe to cabinet
6 V 7 V 8 X 9 V	Hall way near bedgeon	Averter round missing Washing Machine Harks wither when in a was left loose and caved water during e to cabinet Tready sent in 2 (eguests
6 V 7 V 8 X 9 V	Hall way near bedreim Hall way closet P-trap vale kitchen sink	Availed vound missing Washing Machine Haks wider when in a was left loose and caved water dumage to cabinet Theady sent in 2 (eguests

DATE

HOMEOWNER SIGNATURE



LIVE WELL

AMACON CONSTRUCTION SERVICE REQUEST FORM

PLEASE FAX TO 416 369-9068

NAME: M	chael Wurst	
	cond (Wor)	SUITE: /7/2
TEL:		BUS. TEL:
	17-408-8317	E-MAIL:
DATE OF RE	QUEST: 04. 5, 2010	Permission to enter on scheduled date:
of the PDI (F soon as a pos If your conce	ed on the Tarion Warranty guidelin Pre-Delivery Inspection). Your requ ssible. If this is an Emergency pleas	epresentative, this form becomes property of Amacon. Your request les - scratches, nicks, dents are not warrantable, unless noted at time lest will be reviewed and addressed by an Amacon Representative as e contact your concierge immediately at (289) 521-1313 - 24 / hours. Element Warranty Guidelines, please see Property Management to
ITEM#	ROOM/LOCATION	DESCRIPTION
1 ×	Washroom	Side panel of counter Missing
2 1/	Washroom	Buth tub ply not recieved.
3 1	Halling near Goget	Quater round missing, left in close +?
4 1	Hallway Mar bedram	Quater royal missing
5 *	Gosef	Washing Machine kaks at the front phi
		_
SERVICE P	ERSON	



LIVE WELL"

AMACON CONSTRUCTION SERVICE REQUEST FORM

	PLEASE	: FAX 10 416 369-9068
	1 chae Wurst 7-408-831	SUITE: 17/2
•	, , , , , , , , , , , , , , , , , , , ,	BUS. TEL:
	EQUEST: October 5, 20	E-MAIL: Permission to enter on scheduled date:
of the PDI (F soon as a po- lf your conce	ed on the Tarion Warranty guideli Pre-Delivery Inspection). Your req ssible. If this is an <u>Emergency</u> plea	Representative, this form becomes property of Amacon. Your request nes - scratches, nicks, dents are not warrantable, unless noted at time uest will be reviewed and addressed by an Amacon Representative as se contact your concierge <u>immediately</u> at (289) 521-1313 - 24 / hours Element Warranty Guidelines, please see Property Management to 9.
ITEM#	ROOM/LOCATION	DESCRIPTION
	Under Kitchen Sink	PTrap was lowe caused damage to exploase
SERVICE F		Oct. 5 2000

HOMEOWNER SIGNATURE