

A M A C O N**Completed Deficiencies
Elle - Phase: Elle - Lot: 3103**

<u>Date Reported</u>	<u>Type</u>	<u>Number</u>	<u>Deficiency Description</u>	<u>Trade Assigned</u>	<u>Add Trade</u>	<u>Appointment Date</u>
08Sept10	PDI	1	FOYER / ENTRY- - WALLS-touchup walls where indicate <i>complete as per carlos request - Group Close</i>	(Amacon Service)	Add	NoAppoint.
08Sept10	PDI	2	FOYER / ENTRY- - WALLS: 1-outlet not flush <i>complete as per carlos request - Group Close</i>	(Amacon Service)	Add	NoAppoint.
08Sept10	PDI	3	FOYER / ENTRY- - DOORS-bumpy edge of entrance door <i>complete as per carlos request - Group Close</i>	(Amacon Service)	Add	NoAppoint.
08Sept10	PDI	4	LIVING/DINING ROOM- - --scratches on floorboard see stickers <i>completed as per Eds request - Group Close</i>	(Barwood Flooring)	Add	NoAppoint.
08Sept10	PDI	5	LIVING/DINING ROOM- - -: 1-poorly finish stipple in front of bedroom entrance <i>complete as per carlos request - Group Close</i>	(RGM Contractors)	Add	NoAppoint.
08Sept10	PDI	6	LIVING/DINING ROOM- - WINDOWS-gaps around jmold on door and window <i>complete as per carlos request - Group Close</i>	(Amacon Service)	Add	NoAppoint.
08Sept10	PDI	7	LIVING/DINING ROOM- - WINDOWS: 1-balcony door lock sticking <i>complete as per carlos request - Group Close</i>	(Allan Windows)	Add	NoAppoint.
08Sept10	PDI	8	LIVING/DINING ROOM- - WINDOWS: 2-balcony door squeaky <i>complete as per carlos request - Group Close</i>	(Allan Windows)	Add	NoAppoint.
08Sept10	PDI	9	LIVING/DINING ROOM- - WINDOWS: 3-screen is missing <i>complete as per carlos request - Group Close</i>	(Allan Windows)	Add	NoAppoint.
08Sept10	PDI	10	LIVING/DINING ROOM- - WALLS-touchup where indicated <i>complete as per carlos request - Group Close</i>	(Amacon Service)	Add	NoAppoint.
08Sept10	PDI	11	MASTER BEDROOM- - WALLS-touchup where indicated <i>complete as per carlos request - Group Close</i>	(Amacon Service)	Add	NoAppoint.
08Sept10	PDI	12	MASTER BEDROOM- - CLOSET-utility panel hanging open <i>complete as per carlos request - Group Close</i>	(Amacon Service)	Add	NoAppoint.
08Sept10	PDI	13	MASTER BEDROOM- - WINDOWS-gaps around j mold <i>complete as per carlos request - Group Close</i>	(Amacon Service)	Add	NoAppoint.
08Sept10	PDI	14	DEN- - WALLS-touchup walls and baseboard <i>complete as per carlos request - Group Close</i>	(Amacon Service)	Add	NoAppoint.
08Sept10	PDI	15	DEN- - FLOORING-carpet is marked <i>complete as per carlos request - Group Close</i>	(Amacon Service)	Add	NoAppoint.
08Sept10	PDI	16	MAIN BATHROOM- - WALLS-touchup where indicated <i>complete as per carlos request - Group Close</i>	(Amacon Service)	Add	NoAppoint.
08Sept10	PDI	17	MAIN BATHROOM- - DOORS-squeaky entrance door <i>complete as per carlos request - Group Close</i>	(Amacon Service)	Add	NoAppoint.
08Sept10	PDI	18	MAIN BATHROOM- - DOORS: 1-door pin is raised <i>complete as per carlos request - Group Close</i>	(Amacon Service)	Add	NoAppoint.
			MAIN BATHROOM- - TUB-check shower rod			

<div> <div>08Sept10</div> <div>PDI</div> <div>20</div> <div> <div>ends coming apart</div> <div>complete as per carlos request - Group Close</div> </div> </div>			(Amacon Service)	Add	NoAppoint.
08Sept10	PDI	20	KITCHEN- - CABINETS-breakfast bar gable damage in centre completed as per Eds request - Group Close	(Cartier Kitchens)	Add NoAppoint.
08Sept10	PDI	21	KITCHEN- - CABINETS: 1-scratches on door rightside of microwave Complete as per Carlase request - Group Close	(Cartier Kitchens)	Add NoAppoint.
08Sept10	PDI	22	KITCHEN- - CABINETS: 2-shelf not installed in cupboard bottom leftbside at end complete as per carlos request - Group Close	(Amacon Service)	Add NoAppoint.
08Sept10	PDI	23	KITCHEN- - ELECTRICAL/LIGHTING-outlets are loose on both sides of stove complete as per carlos request - Group Close	(Amacon Service)	Add NoAppoint.
08Sept10	PDI	24	KITCHEN- - WALLS-touchup bulkhead above microwave complete as per carlos request - Group Close	(Amacon Service)	Add NoAppoint.
<u>Customer Info</u>	<u>Add a Deficiency</u>	<u>Show Missed Promise Dates</u>	<u>Show Outstanding Deficiencies</u>	<u>Show Appointment Checkboxes</u>	<u>Work Order</u> <u>Forms</u>