


**AMACON**

LIVE WELL

**Warranty Services  
Work Order**

Phone: (905) 848-2069 Fax: (905) 848-2827

<b>Location</b>	<u>Eve - Tower: 1 - Unit: 202</u> <u>202 - 3515 Kariya</u>
<b>Closing Date</b>	<u>0000</u>
<b>Date</b>	<u>19Mar10</u>
<b>Contact Name(s)</b>	<u>Ricardo Mohammed and Mari Mohammed</u>
<b>Contact Telephone#</b>	
<b>Company:</b>	<u>Amacon Service</u>
<b>Attention:</b>	<u>Mark Fritz</u>
<b>Telephone:</b>	
<b>Fax:</b>	<u>9 (052) 32--4637</u>
<b>From:</b>	<u>Warranty Services Department - Head Office</u>

Please complete the following items:			
Deficiency Number	Issue	Appointment Date/Time	Notes
18472	Main Bathroom- Toilet, inside tank - rubber flap is not properly secured		→ CANNOT FIND PROBLEM

Date Completed: \_\_\_\_\_

Amacon Customer Care Signature: \_\_\_\_\_

Please schedule your Service Department to complete work on the above Unit. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative **must have** this form signed by homeowner on completion. Please fax the signed form to our office (905) 848-2827.

Failure to comply with this request will give Amacon Developments (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

[Back - Forms Menu](#)

ID# 18472 Eve Ph 1 Lot 202

*DONE*  
*MARCH 10*

**AMACON**

LIVE WELL

## Warranty Services Work Order

Phone: (905) 848-2069 Fax: (905) 848-2827

*Fritz*

<b>Location</b>	<u>Eve - Tower: 1 - Unit: 202</u> <u>202 - 3515 Kariya</u>
<b>Closing Date</b>	<u>0000</u>
<b>Date</b>	<u>09Mar10</u>
<b>Contact Name(s)</b>	<u>Ricardo Mohammed and Mari Mohammed</u>
<b>Contact Telephone#</b>	
<b>Company:</b>	<u>Amacon Service</u>
<b>Attention:</b>	<u>Mark Fritz</u>
<b>Telephone:</b>	
<b>Fax:</b>	<u>9 (052) 32--4637</u>
<b>From:</b>	<u>Warranty Services Department - Head Office</u>

## Please complete the following items:

Deficiency Number	Issue	Appointment Date/Time	Notes
18287	Bedroom #2- cold draft coming in from electrical outlet and telephone jack outlet space on left side of telephone jack outlet to be repaired / sealed		
18436	Bedroom 2 Ensuite- Toilet tank water control, rubber is loose. Water keeps dripping through		

Date Completed:

*MARCH 10 / 10*

Amacon Customer Care Signature:

*[Signature]*

Please schedule your Service Department to complete work on the above Unit. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative **must have** this form signed by homeowner on completion. Please fax the signed form to our office (905) 848-2827.

Failure to comply with this request will give Amacon Developments (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

[Back - Forms Menu](#)

ID# 18287/18436 Eve Ph 1 Lot 202

*DONE MARCH 10, 2010*

# AMACON DEVELOPMENT

## AMACON SERVICE REQUEST FORM

PLEASE MAIL, FAX OR SUBMIT ON-LINE

AMACON CONSTRUCTION LTD.

2 HARBOUR STREET, TORONTO, ON M5S 1A1

TEL: 905-369-3069 FAX: 905-369-3069 905-232-4637 (For AmacOn)  
905-369-4636 CUSTOMER CARE  
ATTENTION CUSTOMER CARE: 3515 KARIYA DR.

TEL: 905-369-3069 FAX: 905-369-3069

NAME: RICARDO MOHAMMED SITE # 202

DEVELOPMENT NAME: EVE ADDRESS: 3515 KARIYA DRIVE

RES TEL: 905-269-0242 BUS TEL: CELL: 416-885-7962

FAX: EMAIL: ric\_mohammed@yahoo.ca

DATE OF REQUEST: Nov. 20/09

### SERVICE REQUEST:

1. Significant amount of moisture along window CONDENSATION
2. sill and edge of windows in both bedrooms.
- 3.

4. ② Door on kitchen cupboard to align
- 5.

6. ③ Noise heard (cratling/banging noise) LISA
7. when using shower in main bathroom
- 8.
- 9.
- 10.

I give permission to enter my suite for repairs as mentioned above in my absence.

Ricardo Mohammed Nov. 20/09