

LIVE WELL

Warranty Services Work Order


Phone: (905) 848-2069 Fax: (905) 848-2827

Location	<u>Eve - Tower: 1 - Unit: 501</u> <u>501 - 3515 Kariya Mississauga</u>
Closing Date	<u>0000</u>
Date	<u>24Mar10</u>
Contact Name(s)	<u>Melissa Alphonso</u>
Contact Telephone#	
Company:	<u>Amacon Service</u>
Attention:	<u>Mark Fritz</u>
Telephone:	
Fax:	<u>9 (052) 32--4637</u>
From:	<u>Warranty Services Department - Head Office</u>

Please complete the following items:				
Deficiency Number	Issue		Appointment Date/Time	Notes
18491	Bedroom- Visible black marks on both sides of window frame (wall) Also electrical panel needs touch up			

Nothing on panel looks clean

Date Completed: _____



Amacon Customer Care Signature: _____

Please schedule your Service Department to complete work on the above Unit. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative **must have** this form signed by homeowner on completion. Please fax the signed form to our office (905) 848-2827.

Failure to comply with this request will give Amacon Developments (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

[Back - Forms Menu](#)

ID# 18491 Eve Ph 1 Lot 501

Attn: Mark

Completed

AMACON DEVELOPMENT

AMACON SERVICE REQUEST FORM

PLEASE MAIL, FAX OR SUBMIT ON-LINE

AMACON CONSTRUCTION LTD.

2 HARBOR STREET, TORONTO, ON M5S 1B1

TEL: 905-543-2000 FAX: 905-543-2000
or (905) 543-4636

905-232-4637 (Fax to Amaccon)
CUSTOMER CARE

ATTENTION CUSTOMER CARE: 2515 KARIYA DR.

TEL: 905-543-2000 FAX: 905-543-2000

NAME: Melissa Alphonso

SUITE: 501

DEVELOPMENT NAME: Amaccon

ADDRESS: 3515 Kariya Drive Mississauga ON L5B 0C1

RETEL: (416) 408-1612

RETEL: (905) 543-2071

CELL: _____

FAX: _____

EMAIL: melissnicola@hotmail.com

DATE OF REQUEST: January 16, 2010

SERVICE REQUEST:

1. Inner wall in the cupboard on the right of the stove ✓
2. The blue and red label has been switched on the faucet (blue is hot and red is cold) ✓
3. Scratch on the hardwood in the living room ✓
4. Bedroom window on the right and left - scrapes on the wall ✓
5. Washroom Door side has to be sanded ✓
6. Near the sink over the socket - right hand side wall needs to be sealed properly ✓
7. Markings on the bottom of the tub ✓
8. Exterior right panel of the window has excessive caulking in the corner ✓
9. Washer is jumping on spin cycle ✓
10. _____

* You have my permission to go to my Suite and fix all the above defects

Attn: Mark

AMACON DEVELOPMENT

AMACON SERVICE REQUEST FORM

PLEASE MAIL, FAX OR SUBMIT ON-LINE

AMACON CONSTRUCTION LTD.

2 HARBOUR STREET, TORONTO, ON M5J0G1

TEL: 416-363-9069 FAX: 416-363-9069
(905) 882-4636

905-232-4637 (From Amacón)
CUSTOMER CARE

ATTENTION CUSTOMER CARE: 3515 KARIYA DR.

TEL: 905-842-2025 FAX: 905-842-2027

NAME: Melissa Alphonso

SUITE: 501

DEVELOPMENT NAME: Amacón

ADDRESS: 3515 Kariya Drive Mississauga ON L5B 3X1

RES TEL: (647) 408-1612

BUS TEL: (905) 518-3071

CELL: _____

FAX: _____

EMAIL: melisnicola@hotmail.com

DATE OF REQUEST: January 16, 2010

SERVICE REQUEST:

1. Inner wall in the cupboard on the right of the stove
2. The blue and red label has been switched on the faucet (blue is hot and red is cold)
3. Scratch on the hardwood in the living room
4. Bottom window on the right and left - scrapes on the wall
5. Washroom Door side has to be sanded
6. Near the sink over the socket right hand side wall needs to be sealed properly.
7. Markings on the bottom of the tub
8. Extreme right panel of the window has excessive caulking in the bedroom
9. Washer is jumping on spin cycle
10. _____

* You have my permission to go to my Suite and fix all the above defects.