

**A M A C O N**

L I V E   W E L L

**Warranty Services  
Work Order**

Phone: (905) 848-2069 Fax: (905) 848-2827

<b>Location</b>	<u>Eve - Tower: 1 - Unit: 802</u> <u>802 - 3515 Kariya</u>
<b>Closing Date</b>	<u>0000</u>
<b>Date</b>	<u>29Mar10</u>
<b>Contact Name(s)</b>	<u>Christopher H. Parina and Dinah Parina</u>
<b>Contact Telephone#</b>	
<b>Company:</b>	<u>Barwood Flooring</u>
<b>Attention:</b>	
<b>Telephone:</b>	
<b>Fax:</b>	<u>(416) 431-2393</u>
<b>From:</b>	<u>Warranty Services Department - Head Office</u>

Please complete the following items:				
Deficiency Number	Issue		Appointment Date/Time	Notes
18493	Living Room- Visible wide gaps throughout the area		03/31/10	NOT UNDER WARRANTY

NOT UNDER WARRANTY  
 WATER DAMAGED (TENANTS)  
 Date Completed: MARCH 31/10

Amacon Customer Care Signature: [Signature]

Please schedule your Service Department to complete work on the above Unit. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative **must have** this form signed by homeowner on completion. Please fax the signed form to our office (905) 848-2827.

Failure to comply with this request will give Amacon Developments (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

[Back - Forms Menu](#)

ID# 18493 Eve Ph 1 Lot 802

*Done*

*TENANTS HAS COUNTS*

**AMACON**

LIVE WELL

# Warranty Services Work Order

Phone: (905) 848-2069 Fax: (905) 848-2827

**Location** Eve - Tower: 1 - Unit: 802  
**Closing Date** 802 - 3515 Kariya  
**Date** 0000  
**Contact Name(s)** 13Apr10  
**Contact Telephone#** Christopher H. Parina and Dinah Parina  
**Company:** Barwood Flooring  
**Attention:**  
**Telephone:**  
**Fax:** (416) 431-2393  
**From:** Warranty Services Department - Head Office

## Please complete the following items:

Deficiency Number	Issue	Appointment Date/Time	Notes
18493	Living Room- Visible wide gaps throughout the area		

Date Completed:

Amacon Customer Care Signature:

Please schedule your Service Department to complete work on the above Unit. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative **must have** this form signed by homeowner on completion. Please fax the signed form to our office (905) 848-2827.

Failure to comply with this request will give Amacon Developments (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

[Back - Forms Menu](#)

ID# 18493 Eve Ph 1 Lot 802


**A M A C O N**

L I V E   W E L L

**Warranty Services  
Work Order**

Phone: (905) 848-2069 Fax: (905) 848-2827

<b>Location</b>	<u>Eve - Tower: 1 - Unit: 802</u> <u>802 - 3515 Kariya</u>
<b>Closing Date</b>	<u>0000</u>
<b>Date</b>	<u>15Mar10</u>
<b>Contact Name(s)</b>	<u>Christopher H. Parina and Dinah Parina</u>
<b>Contact Telephone#</b>	
<b>Company:</b>	<u>Barwood Flooring</u>
<b>Attention:</b>	
<b>Telephone:</b>	
<b>Fax:</b>	<u>(416) 431-2393</u>
<b>From:</b>	<u>Warranty Services Department - Head Office</u>

Please complete the following items:				
Deficiency Number	Issue		Appointment Date/Time	Notes
18454	Living Room- Hardwood has too many wide gaps throughout		✓	WATER DAMAGE NOT WARRANTABLE.

Date Completed:

Amacon Customer Care Signature:

Please schedule your Service Department to complete work on the above Unit. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative **must have** this form signed by homeowner on completion. Please fax the signed form to our office (905) 848-2827.

Failure to comply with this request will give Amacon Developments (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

Back - Forms Menu

ID# 18454 Eve Ph 1 Lot 802

*FOR*  
 → PLS. REBOOK / NEXT BARWOOD VISIT  
 → EG THIS ONE HERE IS WATER DAMAGE DUE TO IMPROPER MAINTENANCE & NEGLECT DUE TO THE RENTERS → WATER HAS BEEN SPILLED ON THAT FLOOR MORE THAN ONCE I ASSURE YOU...

# AMACON DEVELOPMENT

## AMACON SERVICE REQUEST FORM

PLEASE MAIL, FAX OR SUBMIT ON-LINE

AMACON CONSTRUCTION LTD.

2 HARBOUR STREET, TORONTO, ON M5J 1A1

TEL: 416-363-9885 FAX: 416-363-9885  
OR (905) 882-4636

905-232-4637 (Fax to AmacOn)

CUSTOMER CARE

ATTENTION CUSTOMER CARE: 3515 KARIYA DR.

TEL: 905-882-2885 FAX: 905-882-2887

NAME Nargis Khan

SITE # 802

DEVELOPMENT NAME AmacOn

ADDRESS

3515 Kariya Drive

RETEL: 289-2923241 BUS. TEL: ( )

CELL: 647-838-9070

FAX

EMAIL

DATE OF REQUEST: 2nd 12 2009

SERVICE REQUEST:

1. Shower handle is loose in the
2. washroom
3. all in key!
- 4.
- 5.
- 6.
- 7.
- 8.
- 9.
- 10.

DONE

DEC 16, 09

I give the <sup>permission</sup> ~~opportunity~~ to enter the  
suite and fix \_\_\_\_\_  
\_\_\_\_\_

FILE

**PLEASE READ, FAX OR E-MAIL ON-LINE**

2 HARBOUR STREET, TORONTO, ON M5G 1A1

~~TEL: 415-323-3838 FAX: 415-323-3238~~

TEL: 905-232-4637 FAX: 905-232-4636 905-232-4637 (Forced American)  
 (905) 232-4636 CUSTOMER CARE

ATTENTION CUSTOMER CARE: 800 855 8474 DE

TEL: 505-242-2722 FAX: 505-242-2320

WALSH-

DEVELOPMENT NAME:

0515

**FAX**

DATE OF REQUEST:

**SERVICE REQUEST:**

24

2

24

4

5

5

8.

9.

24

DONE: FEB 17 / 10

~~I give the permission to enter the suite.~~

# AMACON DEVELOPMENT

## AMACON SERVICE REQUEST FORM

PLEASE MAIL, FAX OR SUBMIT ON-LINE

AMACON CONSTRUCTION LTD.

2 HARBOUR STREET, TORONTO, ON M5J3B1

TEL: 416-369-9069 FAX: 416-369-9065 905-232-4637 (Fax to AMACON)  
905-232-4636 CUSTOMER CARE

ATTENTION CUSTOMER CARE: 3515 KARIYA DR.

TEL: 905-848-2069 FAX: 905-848-2827

NAME: Vargis SUITE # 802

DEVELOPMENT NAME: EVE ADDRESS: 3515

RES. TEL: 905-232-3302 BUS. TEL: — CELL: 647-838-9070

FAX: — EMAIL: —

DATE OF REQUEST: 17.08.09

### SERVICE REQUEST:

1. Floor chipped off
2. Cabinets are not proper
3. The rack is wobbly
4. —
5. Bowwood fix floor
6. lifting up
7. —
8. —
9. Aug 19/2009
10. Kitchen rack

I give the permission to enter / come to the apartment Prof

# AMAZON SERVICE REQUEST FORM

**AMALCON CONSTRUCTION LTD.**

TEL: 416-362-9065 FAX: 416-362-9066 905-232-4637 (FAX NO ATTACON)  
 (905) 232-4636 CUSTOMER CARE  
 ATTENTION CUSTOMER CARE: 3515 KANYA DEL.

NAME 1 ariz. Khan SURF 802

DEVELOPMENT NAME: Amazon ADDRESS: 3515 Karing Drive

REF: 289-2323241, REF: 647-838-9070, REF: 647-838-9070

FAX \_\_\_\_\_ EMail: nargis@nargiskhan@yahoo.com

DATE OF REQUEST: 21.11.2009

**SERVICE REQUEST:**

- There are water vapours all over my windows which has turned to fungus or green algae. Please check this is urgent. It has been happening since the last week.

7. Don't

§ 1. \_\_\_\_\_

100

**SECRET**

I give the ~~opportunity~~ permission  
to enter the suite,