

AMACON DEVELOPMENT

AMACON SERVICE REQUEST FORM

PLEASE MAIL, FAX OR SUBMIT ON-LINE

AMACON CONSTRUCTION LTD.

2 HARBOUR STREET, TORONTO, ON M5S 1A1

TEL: 416-363-9009 FAX: 416-363-9005
(905) 882-4636

ATTENTION: CUSTOMER CARE, 3515 KAVYA DR.

TEL: 905-882-2069 FAX: 905-882-2077

NAME: Nicholas Nkomo

SUITE # 2207

DEVELOPMENT NAME: EVE

ADDRESS: 3515 KAVYA DR. TORONTO

RES. TEL: 405 123 1327 BUS. TEL:

CELL:

FAX:

DATE OF REQUEST: 12/NOV/09

SERVICE REQUEST:

1. Kitchen Cabinet - Wood Side by Dishwasher
2. Wood floor - Scratches
3. Bathroom Sink - Not straight Down
4. Toilet Pipe - Not attached to wall

NEXT WORK
CHICK PPT
IN BACK

Althouse Suit Entry
ALC Comp 12/73

Outstanding items
 List all outstanding items covered by the statutory warranty in the table below.
 If you require more space, please make copies of this page, number them
 and attach them to this Statutory Warranty Form.

Outstanding items must be
 specifically listed and described
 A reference to the Pre-Delivery
 Inspection Form or to other
 documentation will not be
 accepted.

Item #	Room/Location	Description
1	All doors	Chauking missing at bottom of door frame.
2	Master Bathroom	Shower curtain rail heat ⇒ replacement
3	Kitchen	Stove ⇒ Missing Grill Pan
4	Living Room	Flooring ⇒ Deep scratches, missing plank, wide space b/w planks
5	Kitchen	Marble counter ⇒ Poor attachment of countertop to cabinets
6	Master Bathroom	Sink-Drain cover not properly attached - poor finishing
7	Master Bathroom	Toilet-Drain cover not properly attached - poor finishing
8	Kitchen	Two kitchen cabinets are missing interior side panels
9	Whole house	Heating Problems ⇒ Thermostat not working.
10	Kitchen	Increasing temperature does not release more heat. faucet - Poor spray - spray handle adjustment

The items specified on this Statutory Warranty Form constitute a complete list of all known warranty items which are outstanding and have not been resolved by my Builder to date.

Homeowner's Signature Kristi Mangel

Date of Signature (YYYYMMDD) 2007103102

Remember to send a copy of this completed Form to your Builder.

Eve - Phase: 1 - Lot: 2207
Editing a Deficiency Assignment

8). LIVING/DINING ROOM- - FLOORING-right side by kitchen entry - 4 boards from wall - scratched - see tape

Date Assigned:	2008-12-30	
Assigned By:	Mark Fritz	
Assigned Via:	Fax	
Assigned Instruction:		
Assigned To:	Barwood Flooring	
Estimated Completion Date	0000-00-00	
Order of Repair:	0	
Closing Notes:		
Completion Date:	2009-01-11	

Eve - Phase: 1 - Lot: 2207
Editing a Deficiency Assignment

9). LIVING/DINING ROOM - - FLOORING: 1-upon entering livingroom - 2' from laundry closet door - floor scratched - see tape

Date Assigned:	2008-12-30	Assigned By:	Mark Fritz	Assigned Via:	Fax	Assigned Instruction:	Barwood Flooring	Estimated Completion Date	0000-00-00	Order of Repair:	0	Closing Notes:		Completion Date:	2009-01-11
Post Cancel															