

AMAZON SERVICE REQUEST FORM

AMACON CONSTRUCTION LTD.

VERY URGENT
HEAT IN UNIT

905-232-4637 (Fax us America!)
CUSTOMER CARE

ATTENTION CUSTOMER CARE: 3515 KANYA DR.

~~TEL: 88-282 FAX: 88-282~~

NAME ENZA MORREALE SUITE 2702

DEVELOPMENT NAME: _____ ADDRESS: _____

DATE: _____ BUS. TEL: _____ CELL: 416-578-0578

FAY: _____ EAL: _____

DATE OF REQUEST: DEC. 9-2009

SERVICE REQUEST:

- ① 1. HEAT IN MAIN AREA (COLD AIR WAS COMING OUT +
2. wiring in fancoil, not now it stopped
3. connected. DECU took WORKING COMPLETELY
4. @ look. and reconnected THERE IS NO DISPLAY
5. fancoil. ON THERMOSTAT)
6. All OK. M.C. Dec 9/09.
- ② 1. VENT NEXT TO FRONT DOOR (IN HALLWAY.)
2. (VERY STRONG + COLD AIR IS COMING OUT
3. OF VENT + WE CAN FEEL THAT COLD AIR
4. IN THE SUITE)
5. OK TO GO INTO SUITE TO REPAIR.
6. Egg M. Moore
7. L-property mgt. needs to
8. put heat up to

AMACON DEVELOPMENT

AMACON SERVICE REQUEST FORM

PLEASE MAIL, FAX OR E-MAIL TO: AMACON

AMACON CONSTRUCTION LTD.

2 HARBOR STREET, TORONTO, ON M5G 1S1

TEL: 416-593-4888 FAX: 416-593-4889 905-232-4633 (Toll Free Amaccon)

ATTENTION: CUSTOMER CARE DEPT. 1-800-463-4889

TEL: 416-593-4888 FAX: 416-593-4889

NAME: AL MORACCA

DEVELOPMENT NAME: Amaccon 2702

ADDRESS: 3515 KENNEDY AVE

CITY: MISSISSAUGA ON L4V 1M1

DATE OF INCIDENT: _____

SERVICE REQUEST: _____

1. Hole under sink: needs to be repaired

(2702)

2. _____

3. _____

4. _____

5. _____

6. _____

7. _____

8. _____

9. _____

10. _____

I Authorize Suite entry - Alma M