Jan Dan

Outstanding Deficiencies Elle - Phase: Elle - Lot: 1007

Date Reported	Type	Number	Number Deficiency Description	Trade Assigned	Add Trade	Appointment Date
27Jul10	Quality Control	63	LIVING/DINING ROOMO.K.	Amacon	Add	Z
273u110	Quality Control	v	MASTER BEDROOM- General- FLOORING: 1-carpet marked in front of window	Amacon Service	Add	No Appoint.
27Jul10	Quality Control	9	DEN O.K.	Amacon Service	. <u>Add</u>	No.Appoint.
27Jul10	Quality Control	, ,	KITCHEN COUNTERTOPS-BACK	Amacon Service	Add	NoAppoint.
273ul10	Quality Control	12	KITCHEN- General- APPLIANCE-scratches on fridge door SERIAL #E010117853	Whirlpool Canada	V dd	NoAppoint
27Jul10	Quality Control	13	KITCHEN- Garage Capping- ELECTRICAL/LIGHTING-kitchen light not working	Amacon Service	Add	No.Appoint.
08Oct10	PDI	p	FOYER / ENTRY FLOORING-threshold lifting @ transition from tile to hard wood	Barwood x Flooring	PPV	NoAppoint
08Oct 10	PDI	7	MASTER BEDROOM DOORS-scrape across top // outer entry door -paint touch up	Amacon	Add	NoAppoint
08Oct 10	PDI	۲n	MASTER BEDROOM FLOORING-stains on carpet in front of window	Amacon Seprice	Add	No.Appoint.
08Oct10	PDĭ	4	MASTER BEDROOM ELECTRICAL/LIGHTING-Life alarm silencer crooked.	\	Add	No Appoint.
08Oct10	PDI	'n	DEN WALLS-gap between baseboard & wall all caross back wall	Amacon Service	Add	No Appoint.
08Oct10	PDI	9	KITCHENCABINETS-left from Microwave inner cabinet dooR paint splatter	Cartier Kitchens	Add	No Appoint.
08Oct10	PDi	7	KITCHEN APPLIANCE-piease assemble inner \mathcal{V} frigde	Amacon Service	Add	NoAppoint.
08Oct 10	PDI	∞	LAUNDRY CLOSET NOTE-light switch does not // work	Amacon Service	Add	NoAppoint
Customer Info	Show Defi	Show Complete Deficiencies Checkboxes	Add a DeficiencyShow Missed Promise DatesShow Completed DeficienciesShow Appointment Checkboxes	w Appointm Checkboxes		Work Order

Sec. (2)