

Outstanding Deficiencies Elle - Phase: Elle - Lot: 317

<u>Date Reported</u>	<u>Type</u>	<u>Number</u>	<u>Deficiency Description</u>	<u>Trade Assigned</u>	<u>Add Trade</u>	<u>Appointment Date</u>
<u>14Feb11</u>	PDI	1 ✓	FOYER / ENTRY - - WALLS-touch up wall behind door and by light switch	<u>Amacon Service</u>	<u>Add</u>	<u>NoAppt.</u>
<u>14Feb11</u>	PDI	2 ✓	FOYER / ENTRY - General- DOORS-door lock does not latch, door closer needs adjustment / squeeks	<u>Amacon Service</u>	<u>Add</u>	<u>NoAppt.</u>
<u>14Feb11</u>	PDI	3 ✓	FOYER / ENTRY - - CEILING-ceiling stipple has a visible crack by PA system	<u>Amacon Service</u>	<u>Add</u>	<u>NoAppt.</u>
<u>14Feb11</u>	PDI	4 ✓	FOYER / ENTRY - General- CLOSET-adjust sliders, hard to slide	<u>Metropolitan Home Products</u>	<u>Add</u>	<u>NoAppt.</u>
<u>14Feb11</u>	PDI	5 ✓	LIVING/DINING ROOM - - FLOORING-visible scratch on 1 board in front of the breakfast bar and visible nick at centre of the room front of telephone jack	<u>Barwood Flooring</u>	<u>Add</u>	<u>NoAppt.</u>
<u>14Feb11</u>	PDI	6 ✓	LIVING/DINING ROOM - - WINDOWS-adjust balcony door inward panel	<u>Allan Windows</u>	<u>Add</u>	<u>NoAppt.</u>
<u>14Feb11</u>	PDI	7 ✓	LIVING/DINING ROOM - - CEILING-visible crack above balcony door	<u>Amacon Service</u>	<u>Add</u>	<u>NoAppt.</u>
<u>14Feb11</u>	PDI	8 ✓	LIVING/DINING ROOM - - WALLS-paint touch up by breakfast bar under telephone jack, also above cable by smoke detector 2nd bedroom	<u>Amacon Service</u>	<u>Add</u>	<u>NoAppt.</u>
<u>14Feb11</u>	PDI	9 ✓	GUEST BEDROOM 1 - - WALLS-touch up above thermostat and south window has 2 visible patches, inside closet and door frame	<u>Amacon Service</u>	<u>Add</u>	<u>NoAppt.</u>
<u>14Feb11</u>	PDI	10 ✓	MASTER BEDROOM - - WALLS-touch up By silencer switch	<u>Amacon Service</u>	<u>Add</u>	<u>NoAppt.</u>
<u>14Feb11</u>	PDI	11 ✓	MASTER BEDROOM - General- DOORS-remove paint - splashes from door handles and caulk doorframe left side outward - visible gap along perimeter of wall and both sides inwards as well.	<u>Amacon Service</u>	<u>Add</u>	<u>NoAppt.</u>
<u>14Feb11</u>	PDI	12 ✓	MAIN BATHROOM - - TUB-shower head is loose	<u>Lisi Mechanical</u>	<u>Add</u>	<u>NoAppt.</u>
<u>14Feb11</u>	PDI	13 ✓	MAIN BATHROOM - - VANITY CABINETS-adjust door/under sink	<u>Cartier Kitchens</u>	<u>Add</u>	<u>NoAppt.</u>
<u>14Feb11</u>	PDI	14 ✓	MAIN BATHROOM - - ELECTRICAL/LIGHTING-light bulb is burned out	<u>Amacon Service</u>	<u>Add</u>	<u>NoAppt.</u>
<u>14Feb11</u>	PDI	15 ✓	KITCHEN - - CABINETS-adjust all door knobs, drawers and remove glue debris from drawers and breakfast bar gable edge and touch up top of gable at centre	<u>Cartier Kitchens</u>	<u>Add</u>	<u>NoAppt.</u>
<u>14Feb11</u>	PDI	16 ✓	KITCHEN - - SINK-temperature of hot water needs to be adjusted	<u>Lisi Mechanical</u>	<u>Add</u>	<u>NoAppt.</u>

[Customer Info](#) [Show Complete Deficiencies Checkboxes](#) [Add a Deficiency](#) [Show Missed Promise Dates](#) [Show Completed Deficiencies](#) [Show Appointment Checkboxes](#) [Work Order Forms](#)