

Grahme Walsh

From: Grahme Walsh
Sent: Monday, April 11, 2011 12:44 PM
To: Mark Fritz
Subject: RE: Elle - 610

That is right -- until we here the report from the PM

From: Mark Fritz
Sent: Monday, April 11, 2011 12:42 PM
To: Grahme Walsh
Subject: Re: Elle - 610

Yes I know that, so were not Touching it right? Her beef is with PM

From: Grahme Walsh
To: Mark Fritz
Sent: Mon Apr 11 09:39:32 2011
Subject: Elle - 610

The repairs are scheduled by Property management - this was an unit affected by the leak

Deficiency History Lot:610 Elle - Phase: Elle


| <u>Work Order Date</u> | <u>Type</u> | <u>Deficiency Description</u> | <u>Trade</u> | <u>Close Date or Status</u> | <u>Days Open</u> |
|------------------------|--------------------------|---|--------------------|-----------------------------|------------------|
| 14Dec10 | 30-Day | Kitchen- kitchen countertop has a visible dent | Tile Source | 07Apr11 | 114 |
| 04Oct10 | Customer Service Request | Kitchen- front of fridge door scratched | Amacon Head Office | 14Dec10 | 71 |
| 04Oct10 | Customer Service Request | Foyer- door needs stopper | Metro Carpentry | 14Dec10 | 71 |
| 04Oct10 | Customer Service Request | Kitchen- gap at bottom of sink cabinet on the back | Cartier Kitchens | 18Oct10 | 14 |
| 22Sept10 | PDI | FOYER / ENTRY- WALLS-scraped wall & baseboard left of washrm entry door | Amacon Service | 27Sept10 | 5 |
| 22Sept10 | PDI | FOYER / ENTRY- DOORS-entry doorframe & door need paint t/u & nail pops where marked. | Amacon Service | 27Sept10 | 5 |
| 22Sept10 | PDI | FOYER / ENTRY- CLOSET-closet doors need to be adjusted | Amacon Service | 27Sept10 | 5 |
| 22Sept10 | PDI | FOYER / ENTRY- ELECTRICAL/LIGHTING-paint on light fixture. | Amacon Service | 27Sept10 | 5 |
| 22Sept10 | PDI | LIVING/DINING ROOM- FLOORING-marks on hardwood panels -middle of living area. 3 panels frm window | Barwood Flooring | 29Nov10 | 68 |
| 22Sept10 | PDI | LIVING/DINING ROOM- WALLS-visible lines & nails in baseboards | Amacon Service | 27Sept10 | 5 |

| | | | | | |
|----------|-----|---|----------------------------|----------|----|
| | | through out. | | | |
| 22Sept10 | PDI | LIVING/DINING ROOM- WALLS: 1-multiple dents in wall where Marked | Amacon Service | 27Sept10 | 5 |
| 22Sept10 | PDI | LIVING/DINING ROOM- WALLS: 2-damage below balcony door | Amacon Service | 27Sept10 | 5 |
| 22Sept10 | PDI | LIVING/DINING ROOM- WALLS: 3-black marks left of balcony door @ ceiling | Amacon Service | 27Sept10 | 5 |
| 22Sept10 | PDI | LIVING/DINING ROOM- WALLS: 4-damage wall around cable jack & electrical outlet left of cable jack | Amacon Service | 27Sept10 | 5 |
| 22Sept10 | PDI | MASTER BEDROOM- WALLS-damage below window | Amacon Service | 27Sept10 | 5 |
| 22Sept10 | PDI | MASTER BEDROOM- WALLS: 1-patch below electrical outlet left of window not finished. | Amacon Service | 27Sept10 | 5 |
| 22Sept10 | PDI | MASTER BEDROOM- DOORS-inner side of door frame damaged where marked | Amacon Service | 27Sept10 | 5 |
| 22Sept10 | PDI | MASTER BEDROOM- DOORS: 1-inner & outer door has rough patches | Amacon Service | 27Sept10 | 5 |
| 22Sept10 | PDI | MASTER BEDROOM- DOORS: 2-inner doorframe left side scraped where marked. | Amacon Service | 27Sept10 | 5 |
| 22Sept10 | PDI | MASTER BEDROOM- CLOSET-outer door frame damaged lower right side. | Metropolitan Home Products | 27Sept10 | 5 |
| 22Sept10 | PDI | MASTER BEDROOM- CLOSET: 1-paint t/u baseboards | Amacon Service | 27Sept10 | 5 |
| 22Sept10 | PDI | MASTER BEDROOM- CLOSET: 2-black mark on wall | Amacon Service | 27Sept10 | 5 |
| 22Sept10 | PDI | MASTER BEDROOM- CLOSET: 3-repaint access panel | Amacon Service | 27Sept10 | 5 |
| 22Sept10 | PDI | MASTER BEDROOM- WINDOWS-scratches through out window frame | Amacon Service | 27Sept10 | 5 |
| 22Sept10 | PDI | DEN- WALLS-gap around phone Jack. | Amacon Service | 27Sept10 | 5 |
| 22Sept10 | PDI | DEN- WALLS: 1-paint t/u around phone jack & electrical outlet. | Amacon Service | 27Sept10 | 5 |
| 22Sept10 | PDI | DEN- WALLS: 2-wall right of closet has dents & scratches where marked. | Barwood Flooring | 27Sept10 | 5 |
| 22Sept10 | PDI | DEN- WALLS: 3-corners right of closet need paint t/u | Amacon Service | 27Sept10 | 5 |
| 22Sept10 | PDI | DEN- WALLS: 4-corner left of bdrm entry door needs paint t/u | Amacon Service | 27Sept10 | 5 |
| 22Sept10 | PDI | MAIN BATHROOM- DOORS-damage door & doorframe through out Marked. | Amacon Service | 27Sept10 | 5 |
| 22Sept10 | PDI | MAIN BATHROOM- TUB-gaps in caulking around tub | Amacon Service | 27Sept10 | 5 |
| 22Sept10 | PDI | MAIN BATHROOM- COUNTERTOPS-right side of counter top damaged & messy caulking | Amacon Service | 14Dec10 | 83 |
| 22Sept10 | PDI | MAIN BATHROOM- FLOORING-paint on tiles left side of tub. | Amacon Service | 27Sept10 | 5 |
| 22Sept10 | PDI | MAIN BATHROOM- ELECTRICAL/LIGHTING-paint on light switches | Amacon Service | 27Sept10 | 5 |
| 22Sept10 | PDI | KITCHEN- CABINETS-lower right edge of kitchen island not finished. | Cartier Kitchens | 18Oct10 | 26 |
| 22Sept10 | PDI | KITCHEN- CABINETS: 1-right of microwave lower cabinet scratched inside where marked | Cartier Kitchens | 18Oct10 | 26 |
| 22Sept10 | PDI | KITCHEN- CABINETS: 2-above microwave rubbing | Cartier Kitchens | 18Oct10 | 26 |
| 22Sept10 | PDI | KITCHEN- CABINETS: 3-left of microwave screws inside cabinet @ corner instead of back | Cartier Kitchens | 14Dec10 | 83 |
| 22Sept10 | PDI | KITCHEN- CABINETS: 4-extra screw hole left side of cabinet left of microwave. | Cartier Kitchens | 18Oct10 | 26 |
| 22Sept10 | PDI | KITCHEN- CABINETS: 5-top drawer scratches inside. | Cartier Kitchens | 18Oct10 | 26 |
| 22Sept10 | PDI | KITCHEN- CABINETS: 6-gap between back of kitchen island & quarter round. -middle | Cartier Kitchens | 14Dec10 | 83 |
| 22Sept10 | PDI | KITCHEN- CABINETS: 7-below sink left door scratched @ bottom | Cartier Kitchens | 18Oct10 | 26 |

| | | | | | |
|----------|-----|--|------------------|----------|----|
| 22Sept10 | PDI | KITCHEN- CABINETS: 8-far right of sink Need to be adjusted. | Cartier Kitchens | 18Oct10 | 26 |
| 22Sept10 | PDI | KITCHEN- COUNTERTOPS-scratched edge Closest to living area left Side -marked | Cartier Kitchens | 18Oct10 | 26 |
| 22Sept10 | PDI | KITCHEN- APPLIANCE-fridge door scratched | Whirlpool Canada | 14Dec10 | 83 |
| 22Sept10 | PDI | KITCHEN- APPLIANCE: 1-paint splatter On fridge. | Amacon Service | 27Sept10 | 5 |
| 22Sept10 | PDI | KITCHEN- WALLS-baseboard & quarter round paint t/u | Amacon Service | 27Sept10 | 5 |
| 22Sept10 | PDI | LAUNDRY CLOSET- --inside dryer dirty -yellow marks | Amacon Service | 18Oct10 | 26 |
| 22Sept10 | PDI | LAUNDRY CLOSET- DOORS-paint t/u outer entry door | Amacon Service | 27Sept10 | 5 |
| 22Sept10 | PDI | BALCONY- --door has paint splatter & needs to be cleaned. | Amacon Service | 27Sept10 | 5 |

GRAHME WALSH

CONTRACTS/ CUSTOMER SERVICE MANAGER, CONSTRUCTION



L I V E W E L L

37 Bay Street, Suite 400,

Toronto, ON, M5J 3B2

Tel. 416.369.9069

Fax. 416.369.9068

Email. gwalsh@amacon.com

Web. www.amacon.com

This e-mail is intended only for the named recipient(s) and may contain information that is privileged, confidential and/or exempt from disclosure under applicable law. No waiver of privilege, confidence or otherwise is intended by virtue of communication via the Internet. Any unauthorized use, dissemination or copying is strictly prohibited. If you have received this e-mail in error, or are not named as a recipient, please immediately notify the sender and destroy all copies of this e-mail. Please be aware that Internet communications are subject to the risk of data corruption and other transmission errors. For information of extraordinary sensitivity, we recommend that our clients use encryption software when they communicate with us by e-mail.



LIVE WELL

AMACON CONSTRUCTION SERVICE REQUEST FORM

PLEASE FAX TO 416 369-9068

NAME: CARM TASSONE SUITE: 610
TEL: 416-568-0188 BUS. TEL: _____
Cell: _____ e-mail: _____
Project: _____ Address: _____

DATE OF REQUEST: Apr. 11, 2011 Permission to enter:

| | |
|-------------------------------------|--------------------------|
| YES | NO |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Once received by an Amacon Customer Care Representative, this form becomes property of Amacon. Your request must be based on the Taron Warranty guidelines - scratches, nicks, dents are not warrantable, unless noted at time of the PDI (Pre-Delivery Inspection). Your request will be reviewed and addressed by an Amacon Representative as soon as a possible. If this is an **Emergency** please contact your concierge **immediately** at (905) 232-2631 - 24 / hours. If your concern falls under the Common Area Element Warranty Guidelines, please see Property Management to address your concerns or call at (905) 232-2374.

| ITEM# | ROOM/LOCATION | DESCRIPTION |
|-------|----------------------|------------------------------------|
| 1 | Door Entrance | Replace thresh hold - due to flood |
| 2 | Exterior Doorframe | Needs painting of brown area |
| 3 | Front Door | Lower right hand repair |
| 4 | Windows - front room | Loud wind noise and whistling |
| | | |
| | | |
| | | |
| | | |

Property Management
PM/Common Area
Common Area
investigate noise/
GW
04/12/2011

C. Tassone
HOMEOWNER SIGNATURE

April 11, 2011
DATE:

Grahme Walsh

From: Grahme Walsh
Sent: Monday, April 11, 2011 8:36 PM
To: Mark Fritz
Cc: Moe Santos
Subject: Fw: FW: Elle #610

Mark:

Please review the mark ups in red from property management:

- 1) Property management
- 2) Please review all pdi, 30 day requests - I have not noted any crack mirror/ cracked mirror slider
- 3) Property management
- 4) Investigate caulking?
- 5) Investigate - this may or may not be related to our trades

Thanks

Grahme Walsh
Contracts Manager
Amacon Construction Ltd
Cell: 647-333-4802
Office: 416-369-9069

From: Parvi Kaur <parvikaur@verumest.ca>
To: Grahme Walsh
Sent: Mon Apr 11 15:15:57 2011
Subject: re: FW: Elle #610

See my comments in red. This unit was damaged during flood. I think we should discuss about this unit, as I'm been in communication with the residents and some of the information you should be aware of.

Thank you,

Parvi Kaur
Property Manager

Eden Park - P.S.C.C. No. 802

3504 Hurontario Street, Mississauga, ON, L5B 0B9
Tel: (905) 276-1908
Fax: (905) 276-9794

Eve - P.S.C.C. No. 853

3515 Kariya Drive, Mississauga, ON, L5B 0C1
Tel: (905) 232-2374
Fax: (905) 232-1357

Elle - P.S.C.C. No. 889

3525 Kariya Drive, Mississauga, ON, L5B 0C2
Tel: (289) 521-1199

Fax: (289) 521-1400

Email: parvikaur@verumest.ca

Save a tree...please do not print this e-mail unless necessary.

Hey So I got a call from the owner of this unit

She has the following problems with her unit:

- Baseboard behind toilet is damaged. - flood related
- Broken mirror behind closet(contractors broke it) - none of our staff or contractor broke it
- All Frame doors (top corner) damaged - not related to flood
- Baseboard around unit still have nail holes appearing (haven't been covered properly) - might be related to us
- her windows need caulking - not related to us
- Baseboards where they were cut are sticking out. - ???

She has been dealing with property management but no one has helped her, she is very frustrated.

RECEIVED
March 14, 2011
R.F.

AMACON

LIVE WELL

ELLE

Made to
Review
SW
03/15/2011

AMACON CONSTRUCTION SERVICE REQUEST FORM

PLEASE FAX TO 416 369-9068

NAME: Carm Tassore

SUITE: 610

TEL: (4) 568-0188

BUS. TEL: _____

Cell: _____

e-mail: _____

Project: _____

Address: _____

DATE OF REQUEST: March 14 11 Permission to enter:

| YES | NO |
|--------------------------|--------------------------|
| <input type="checkbox"/> | <input type="checkbox"/> |

Once received by an Amacon Customer Care Representative, this form becomes property of Amacon. Your request must be based on the Taron Warranty guidelines - scratches, nicks, dents are not warrantable, unless noted at time of the PDI (Pre-Delivery Inspection). Your request will be reviewed and addressed by an Amacon Representative as soon as a possible. If this is an **Emergency** please contact your concierge **immediately** at (905) 232-2631 - 24 / hours. If your concern falls under the Common Area Element Warranty Guidelines, please see Property Management to address your concerns or call at (905) 232-2374.

| ITEM# | ROOM/LOCATION | DESCRIPTION |
|-------|---------------|---|
| | FRONT DOOR | FRONT DOOR LOCK IS VERY STICKY AND HARD TO OPEN/CLOSE |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |

HOMEOWNER SIGNATURE _____

DATE: _____

RM 15/11

Complete
x freshly painted



LIVE WELL

AMACON CONSTRUCTION SERVICE REQUEST FORM

PLEASE FAX TO 416 369-9068

NAME: CARM Tassone SUITE: 610
TEL: 416-568-0188 BUS. TEL: _____
Cell: _____ e-mail: _____
Project: _____ Address: _____

DATE OF REQUEST: Apr. 11 '2011 Permission to enter:

| | |
|-------------------------------------|--------------------------|
| YES | NO |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Once received by an Amacon Customer Care Representative, this form becomes property of Amacon. Your request must be based on the Tarion Warranty guidelines - scratches, nicks, dents are not warrantable, unless noted at time of the PDI (Pre-Delivery Inspection). Your request will be reviewed and addressed by an Amacon Representative as soon as a possible. If this is an **Emergency** please contact your concierge **immediately** at (905) 232-2631 - 24 / hours. If your concern falls under the Common Area Element Warranty Guidelines, please see Property Management to address your concerns or call at (905) 232-2374.

| ITEM# | ROOM/LOCATION | DESCRIPTION |
|-------|----------------------|------------------------------------|
| 1 | Door Entrance | Replace thresh hold - due to flood |
| 2 | Exterior Doorframe | Needs painting of brown area |
| 3 | Front Door | Lower right hand repair |
| 4 | Windows - front room | Loud wind noise and whistling |
| | | |
| | | |
| | | |
| | | |

Property Management
Pre/Comm. Area
Common Area
investigate noise/
GW
04/12/2011

C. Tassone
HOMEOWNER SIGNATURE

April 11, 2011
DATE:

Grahme Walsh

From: Grahme Walsh
Sent: Monday, April 11, 2011 8:36 PM
To: Mark Fritz
Cc: Moe Santos
Subject: Fw: FW: Elle #610

Mark:

Please review the mark ups in red from property management:

- 1) Property management
- 2) Please review all pdi, 30 day requests - I have not noted any crack mirror/ cracked mirror slider
- 3) Property management
- 4) Investigate caulking?
- 5) Investigate - this may or may not be related to our trades

Thanks

Grahme Walsh
Contracts Manager
Amacon Construction Ltd
Cell: 647-333-4802
Office: 416-369-9069

From: Parvi Kaur <parvikaur@verumest.ca>
To: Grahme Walsh
Sent: Mon Apr 11 15:15:57 2011
Subject: re: FW: Elle #610

See my comments in red. This unit was damaged during flood, I think we should discuss about this unit, as I'm been in communication with the residents and some of the information you should be aware of.

Thank you,

Parvi Kaur
Property Manager

Eden Park - P.S.C.C. No. 802
3504 Hurontario Street, Mississauga, ON, L5B 0B9
Tel: (905) 276-1908
Fax: (905) 276-9794


Eve - P.S.C.C. No. 853
3515 Kariya Drive, Mississauga, ON, L5B 0C1
Tel: (905) 232-2374
Fax: (905) 232-1357

Elle - P.S.C.C. No. 889
3525 Kariya Drive, Mississauga, ON, L5B 0C2
Tel: (289) 521-1199

| | | | | | |
|----------|-----|--|------------------|----------|----|
| 22Sept10 | PDI | KITCHEN- CABINETS: 8-far right of sink Need to be adjusted. | Cartier Kitchens | 18Oct10 | 26 |
| 22Sept10 | PDI | KITCHEN- COUNTERTOPS-scratched edge Closest to living area left Side -marked | Cartier Kitchens | 18Oct10 | 26 |
| 22Sept10 | PDI | KITCHEN- APPLIANCE-fridge door scratched | Whirlpool Canada | 14Dec10 | 83 |
| 22Sept10 | PDI | KITCHEN- APPLIANCE: 1-paint splatter On fridge. | Amacon Service | 27Sept10 | 5 |
| 22Sept10 | PDI | KITCHEN- WALLS-baseboard & quarter round paint t/u | Amacon Service | 27Sept10 | 5 |
| 22Sept10 | PDI | LAUNDRY CLOSET- --inside dryer dirty -yellow marks | Amacon Service | 18Oct10 | 26 |
| 22Sept10 | PDI | LAUNDRY CLOSET- DOORS-paint t/u outer entry door | Amacon Service | 27Sept10 | 5 |
| 22Sept10 | PDI | BALCONY- --door has paint splatter & needs to be cleaned. | Amacon Service | 27Sept10 | 5 |

GRAHME WALSH

CONTRACTS/ CUSTOMER SERVICE MANAGER, CONSTRUCTION



L I V E W E L L

37 Bay Street, Suite 400,

Toronto, ON, M5J 3B2

Tel. 416.369.9069

Fax. 416.369.9068

Email. gwalsh@amacon.com

Web. www.amacon.com

This e-mail is intended only for the named recipient(s) and may contain information that is privileged, confidential and/or exempt from disclosure under applicable law. No waiver of privilege, confidence or otherwise is intended by virtue of communication via the Internet. Any unauthorized use, dissemination or copying is strictly prohibited. If you have received this e-mail in error, or are not named as a recipient, please immediately notify the sender and destroy all copies of this e-mail. Please be aware that Internet communications are subject to the risk of data corruption and other transmission errors. For information of extraordinary sensitivity, we recommend that our clients use encryption software when they communicate with us by e-mail.

610

Outstanding Deficiencies Elle - Phase: Elle - Lot: 610

| <u>Date Reported</u> | <u>Type</u> | <u>Number</u> | <u>Deficiency Description</u> | <u>Trade Assigned</u> | <u>Add Trade</u> | <u>Appointment Date</u> |
|----------------------|-------------|---------------|---|----------------------------|------------------|-------------------------|
| <u>22Sept10</u> | PDI | 1 | FOYER / ENTRY- - WALLS-scraped wall & baseboard left of washrm entry door ✓ | Amacon Service | Add | NoAppoint. |
| <u>22Sept10</u> | PDI | 2 | FOYER / ENTRY- - DOORS-entry doorframe & door need paint t/u & nail pops where marked. ✓ | Amacon Service | Add | NoAppoint. |
| <u>22Sept10</u> | PDI | 3 | FOYER / ENTRY- - CLOSET-closet doors need to be adjusted ✓ | Amacon Service | Add | NoAppoint. |
| <u>22Sept10</u> | PDI | 4 | FOYER / ENTRY- - ELECTRICAL/LIGHTING-paint on light fixture. ✓ | Amacon Service | Add | NoAppoint. |
| <u>22Sept10</u> | PDI | 5 | LIVING/DINING ROOM- - FLOORING-marks on hardwood panels -middle of living area. 3 panels frm window ✗ | Barwood Flooring | Add | NoAppoint. |
| <u>22Sept10</u> | PDI | 6 | LIVING/DINING ROOM- - WALLS-visible lines & nails in baseboards through out. ✓ | Amacon Service | Add | NoAppoint. |
| <u>22Sept10</u> | PDI | 7 | LIVING/DINING ROOM- - WALLS: 1-multiple dents in wall where Marked ✓ | Amacon Service | Add | NoAppoint. |
| <u>22Sept10</u> | PDI | 8 | LIVING/DINING ROOM- - WALLS: 2-damage below balcony door ✓ | Amacon Service | Add | NoAppoint. |
| <u>22Sept10</u> | PDI | 9 | LIVING/DINING ROOM- - WALLS: 3-black marks left of balcony door @ ceiling ✓ | Amacon Service | Add | NoAppoint. |
| <u>22Sept10</u> | PDI | 10 | LIVING/DINING ROOM- - WALLS: 4-damage wall around cable jack & electrical outlet left of cable jack ✓ | Amacon Service | Add | NoAppoint. |
| <u>22Sept10</u> | PDI | 11 | MASTER BEDROOM- - WALLS-damage below window ✓ | Amacon Service | Add | NoAppoint. |
| <u>22Sept10</u> | PDI | 12 | MASTER BEDROOM- - WALLS: 1-patch below electrical outlet left of window not finished. ✓ | Amacon Service | Add | NoAppoint. |
| <u>22Sept10</u> | PDI | 13 | MASTER BEDROOM- - DOORS-inner side of door frame damaged where marked ✓ | Amacon Service | Add | NoAppoint. |
| <u>22Sept10</u> | PDI | 14 | MASTER BEDROOM- - DOORS: 1-Inner & outer door has rough Patches ✓ | Amacon Service | Add | NoAppoint. |
| <u>22Sept10</u> | PDI | 15 | MASTER BEDROOM- - DOORS: 2-inner doorframe left side scraped where marked. ✓ | Amacon Service | Add | NoAppoint. |
| <u>22Sept10</u> | PDI | 16 | MASTER BEDROOM- - CLOSET-outer door frame damaged lower right Side. ✓ | Metropolitan Home Products | Add | NoAppoint. |
| <u>22Sept10</u> | PDI | 17 | MASTER BEDROOM- - CLOSET: 1-paint t/u baseboards ✓ | Amacon Service | Add | NoAppoint. |
| <u>22Sept10</u> | PDI | 18 | MASTER BEDROOM- - CLOSET: 2-black mark on wall ✓ | Amacon Service | Add | NoAppoint. |
| <u>22Sept10</u> | PDI | 19 | MASTER BEDROOM- - CLOSET: 3-repaint access panel ✓ | Amacon Service | Add | NoAppoint. |
| <u>22Sept10</u> | PDI | 20 | MASTER BEDROOM- - WINDOWS-scratches through out window frame ✓ | Amacon Service | Add | NoAppoint. |
| <u>22Sept10</u> | PDI | 21 | DEN- - WALLS-gap around phone Jack. ✓ | Amacon Service | Add | NoAppoint. |
| <u>22Sept10</u> | PDI | 22 | DEN- - WALLS: 1-paint t/u around phone jack & electrical outlet. ✓ | Amacon Service | Add | NoAppoint. |
| <u>22Sept10</u> | PDI | 23 | DEN- - WALLS: 2-wall right of Closet has dents & scratches where marked. ✓ | Barwood Flooring | Add | NoAppoint. |
| <u>22Sept10</u> | PDI | 24 | DEN- - WALLS: 3-corners right of closet need paint t/u ✓ | Amacon Service | Add | NoAppoint. |
| <u>22Sept10</u> | PDI | 25 | DEN- - WALLS: 4-corner left of bdrm entry door needs paint t/u ✓ | Amacon Service | Add | NoAppoint. |

| | | | | | | |
|-----------------|-----|----|---|---|------------|-------------------|
| <u>22Sept10</u> | PDI | 26 | MAIN BATHROOM- - DOORS-damage door & doorframe through out Marked. ✓ | <u>Amacon Service</u> | <u>Add</u> | <u>NoAppoint.</u> |
| <u>22Sept10</u> | PDI | 27 | MAIN BATHROOM- - TUB-gaps in caulking around tub ✓ | <u>Amacon Service</u> | <u>Add</u> | <u>NoAppoint.</u> |
| <u>22Sept10</u> | PDI | 28 | MAIN BATHROOM- - COUNTERTOPS-right Side of counter top damaged & messy caulking ✓ | <u>Cartier Kitchens</u> <u>Amacon Service</u> | <u>Add</u> | <u>NoAppoint.</u> |
| <u>22Sept10</u> | PDI | 29 | MAIN BATHROOM- - FLOORING-paint on tiles left side of tub. ✓ | <u>Amacon Service</u> | <u>Add</u> | <u>NoAppoint.</u> |
| <u>22Sept10</u> | PDI | 30 | MAIN BATHROOM- - ELECTRICAL/LIGHTING-paint on light switches ✓ | <u>Amacon Service</u> | <u>Add</u> | <u>NoAppoint.</u> |
| <u>22Sept10</u> | PDI | 31 | KITCHEN- - CABINETS-lower right edge of Kitchen island not finished. * | <u>Cartier Kitchens</u> | <u>Add</u> | <u>NoAppoint.</u> |
| <u>22Sept10</u> | PDI | 32 | KITCHEN- - CABINETS: 1-right of Microwave lower cabinet scratched inside where marked * | <u>Cartier Kitchens</u> | <u>Add</u> | <u>NoAppoint.</u> |
| <u>22Sept10</u> | PDI | 33 | KITCHEN- - CABINETS: 2-above microwave rubbing * | <u>Cartier Kitchens</u> | <u>Add</u> | <u>NoAppoint.</u> |
| <u>22Sept10</u> | PDI | 34 | KITCHEN- - CABINETS: 3-left of microwave screws inside cabinet @ corner instead of back * | <u>Cartier Kitchens</u> | <u>Add</u> | <u>NoAppoint.</u> |
| <u>22Sept10</u> | PDI | 35 | KITCHEN- - CABINETS: 4-extra screw hole left side of cabinet left of microwave. * | <u>Cartier Kitchens</u> | <u>Add</u> | <u>NoAppoint.</u> |
| <u>22Sept10</u> | PDI | 36 | KITCHEN- - CABINETS: 5-top drawer scratches inside. * | <u>Cartier Kitchens</u> | <u>Add</u> | <u>NoAppoint.</u> |
| <u>22Sept10</u> | PDI | 37 | KITCHEN- - CABINETS: 6-gap between back of Kitchen island & quarter round. -middle * | <u>Cartier Kitchens</u> | <u>Add</u> | <u>NoAppoint.</u> |
| <u>22Sept10</u> | PDI | 38 | KITCHEN- - CABINETS: 7-below sink left door scratched @ bottom * | <u>Cartier Kitchens</u> | <u>Add</u> | <u>NoAppoint.</u> |
| <u>22Sept10</u> | PDI | 39 | KITCHEN- - CABINETS: 8-far right of sink Need to be adjusted. * | <u>Cartier Kitchens</u> | <u>Add</u> | <u>NoAppoint.</u> |
| <u>22Sept10</u> | PDI | 40 | KITCHEN- - COUNTERTOPS-scratched edge Closest to living area left Side -marked * | <u>Cartier Kitchens</u> | <u>Add</u> | <u>NoAppoint.</u> |
| <u>22Sept10</u> | PDI | 41 | KITCHEN- - APPLIANCE-fridge door scratched * | <u>Whirlpool Canada</u> | <u>Add</u> | <u>NoAppoint.</u> |
| <u>22Sept10</u> | PDI | 42 | KITCHEN- - APPLIANCE: 1-paint splatter On fridge. ✓ | <u>Amacon Service</u> | <u>Add</u> | <u>NoAppoint.</u> |
| <u>22Sept10</u> | PDI | 43 | KITCHEN- - WALLS-baseboard & quarter round paint t/u ✓ | <u>Amacon Service</u> | <u>Add</u> | <u>NoAppoint.</u> |
| <u>22Sept10</u> | PDI | 44 | LAUNDRY CLOSET- - --inside dryer dirty - yellow marks * | <u>Whirlpool</u> <u>Amacon Service</u> | <u>Add</u> | <u>NoAppoint.</u> |
| <u>22Sept10</u> | PDI | 45 | LAUNDRY CLOSET- - DOORS-paint t/u outer entry door ✓ | <u>Amacon Service</u> | <u>Add</u> | <u>NoAppoint.</u> |
| <u>22Sept10</u> | PDI | 46 | BALCONY- - --door has paint splatter & needs to be cleaned. ✓ | <u>Amacon Service</u> | <u>Add</u> | <u>NoAppoint.</u> |

Customer Info

Show Complete Deficiencies Checkboxes

Add a Deficiency

Show Missed Promise Dates

Show Completed Deficiencies

Show Appointment Checkboxes

Work Order

Forms

4

JOB
Sept 24