

Outstanding Deficiencies Elle - Phase: Elle - Lot: 907

Date Reported	Type	Number	Deficiency Description	Trade	Add Appointment	Assigned Date
26Jul10	Quality Control	6	DEN. - O.K.	Amaco Service	Add	No Appointment
06Jan11	PDI	1	FOYER / ENTRY - WALLS-touch up walls	Amaco Service	Add	No Appointment
06Jan11	PDI	2	LIVING/DINING ROOM - FLOORING-remove glue debris throughout	Barwood Flooring	Add	No Appointment
06Jan11	PDI	3	MASTER BEDROOM - DOORS-remove paint from the locks	Amaco Service	Add	No Appointment
06Jan11	PDI	4	MASTER BEDROOM - WINDOWS-east side window needs caulking and cleaning on the outer side	Allan Windows	Add	No Appointment
06Jan11	PDI	5	MAIN BATHROOM - FLOORING-remove construction debris from tile	Amaco Service	Add	No Appointment
06Jan11	PDI	6	KITCHEN - CABINETS-adjust all doors, drawers to be aligned, also clean up along perimeter of breakfast bar gable / wall	Cartier Kitchens	Add	No Appointment
06Jan11	PDI	7	KITCHEN - APPLIANCE-visible marks on fridge at the top serial #E00809948	Whirlpool Canada	Add	No Appointment
06Jan11	PDI	8	KITCHEN - ELECTRICAL/LIGHTING-2 light bulbs burned out	Amaco Service	Add	No Appointment
06Jan11	PDI	9	KITCHEN - WINDOWS-ALUMINUM THRESHOLD	Allan Windows	Add	No Appointment

Customer Info
06Jan11
PDI
Show Complete Deficiencies Checkboxes
Add a Deficiency
Show Missed Promise Dates
Show Completed Deficiencies
Show Appointment Checkboxes
Work Order
Forms