

QUALITY RUGS OF CANADA LIMITED REPAIR ORDER

BUILDER: AMACON JOB SITE: ELLE LOT: 908
 COMPLAINT DATE: 7/27/2010
 INSTALLER: OSA
 LAST NAME:
 FIRST NAME:
 CIVIC ADD 1:
 CIVIC ADD 2: TORONTO
 SITE CONTACT: SITE 9.232.4636
 REPAIRMAN:
 REPAIR TYPE: DEFICIENCY REFERENCE 19841
 REP SCHEDULED
 VISIBLE SEAMS IN CARPET IN FRONT OF WINDOW IN GUEST BED.
 DATE: 4/26/2010
 OWNER'S HOME PHONE:
 OWNER'S BUS. PHONE:
 REPAIR TIME:
 EUE 408

INSTALLER'S SIGNATURE
 SUPER/OWNER'S SIGNATURE
 DATE: 25th August 2010

NOTE*** Please have this memo signed by the owner or site super upon completion and forward it to Quality's Head Office. Repairs must be completed within 3 working days of receipt of this repair order.

Paycheques!!!! may be held if work is not completed within the required time.