


ELC 1110

Feb 07 / 2012

LWT trap.



Elb 1110

Feb 07/2012

Tab / Shimmed

Spray Formed

Tub has been

Secured

SG



E1121110

PAINT HAS BEEN
CLEANED (at cully)
PAINT TOUCH UP
HAS BEEN COMPLETE

FEB 07 / 2012.

✓

Ellello

Washroom/ Bathroom

Door Settlement

Crades have been

Completed

Feb 07/2012

Gj

EME 1116

Bathroom Door/
trim - gutt
crack

Complete

Feb 07/2012

SL

