

Elle #1603

Leak Under Sink

Before Picture #2

Date of inspection: May 29th, 2012.

Evidence of Mold.





Elle #1603

After picture #2

Date of inspection: May 29th, 2012.

Mold was removed May 29th, 2012.

