



# AMACON CONSTRUCTION SERVICE REQUEST FORM

PLEASE FAX TO 416 369-9068

NAME Safa Namik SUITE 910  
TEL 289-2327634 BUS TEL \_\_\_\_\_  
Cell 289-2327634 e-mail: \_\_\_\_\_  
Project \_\_\_\_\_ Address: \_\_\_\_\_

DATE OF REQUEST: Aug 28th Permission to enter: YES ☒ NO ☐

Once received by an Amacon Customer Care Representative, this form becomes property of Amacon. Your request must be based on the Taron Warranty guidelines - scratches, nicks, dents are not warrantable, unless noted at time of the PDI (Pre Delivery Inspection). Your request will be reviewed and addressed by an Amacon Representative as soon as a possible. If this is an Emergency please contact your concierge immediately at (289) 521-1313 - 24 / hours. If your concern falls under the Common Area Element Warranty Guidelines, please see Property Management to address your concerns or call at (289) 521-1199.

ITEM#	ROOM/LOCATION	DESCRIPTION
	LIVING ROOM	FAN COIL UNIT NOT WORKING (FAN) HAS POWER, WAS WORKING YESTERDAY WHEN TECHNICIAN HERE BY THE TIME OWNER GOT HOME, IT STOPPED. MARCO (SUPER) HAS ATTENDED UNIT AND CONFIRMED ISSUE and, Aug 28th 2012

HOMEOWNER SIGNATURE \_\_\_\_\_  
DATE: \_\_\_\_\_