

Agincourt Roofing Limited
40 Melford Drive, Unit 8
Scarborough, ON, M1B 2G2
Tel: (416) 298-3333
Fax: (416) 298-9076
e-mail: mail@aginroof.ca

JOB NO.: _____

Report Prepared By: Kevin Kellar

CUSTOMER: History Hill Group ATTN.: Marriam (John)

PROJECT: 3650 Major Mackenzie Drive, Vaughan

TENANT: Berlin Doner

We wish to thank you for your instructions made on Feb. 27, 2020 to attend to the leak problem at the above subject property.

We attended on Feb. 28, 2020 and we are pleased to submit our report as follows:

OUR FINDINGS:

- * "Leak was caused by a problem not related to the roof"
- ☐ Door / Window / Skylight
 - ☐ Exterior wall / Brick & Block / Caulking
 - ☐ Drainage - Roof Drain / Drain Backup / Plugged Drain / Blocked Drain Strainers
 - ☐ Air Conditioner Unit Problem / Pitch Pocket / Duct Covers / Equipment Problem
 - * ☐ Heat Chimney / Storm Collar (Plumbing Vent) Sprinkler Pipe / Heating vent pipe
 - ☐ Other _____
- "Roofing related problems"
- ☐ Caulking Wall Flashing / Coving Flashing / Joint
 - ☐ Membrane Flashing - Coving / Wall / Curb / Sleeper / Cone
 - ☐ Sheet Metal Flashing
 - ☐ Roof Membrane Defect - Split / Punctures / Damages / Blister / Ridges
 - ☐ Expansion Joint Flashing / Control Joint Flashing
 - ☐ Other _____

RECOMMENDATION:

- * To reseal a plumbing vent 3" with M-1 sealant.
- _____
- _____
- _____
- _____

ACTION TAKEN: ☐ Attempted for temporary repair.
☒ Work completed.
☐ Other _____

Service call to attend temporary leak repair N/C
Cost to carry out repair work as noted above will be N/C
TOTAL COST N/C plus HST

** Please fax this report back for your authorization to proceed with the work** Date Accepted

Purchaser

** We will carry out the work upon receipt of your authorization.

** In the event roof holds water, we are unable to carry out the work till water to drain off.

** All the work schedule is subject to weather.