Enrollment:

Purchaser Name: Thi KIM ANH NGUYEN

Thi KIM ANH NGUYEN

 Phone:
 (416) 909-2652

 Phone:
 (416) 909-6466

 Closing Date:
 June 22, 2021

 Inspector:
 Chris Bergman



PDI

Vendor/Builder No.: 39348

Vendor: Lormel Developments (Bradford) Ltd

Lot/Phase: 102 / 2

51M-1087

Address: 271 Chelsea Crescent

Municipality: Town of Bradford West Gwillimbury

Inspection Date: June 15, 2021

Page 1 of 2

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- Bathtub sinks and toilets
- Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- · Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

GENERAL COMMENTS		
NOTE:	TOUCH UPS REQUIRED THROUGH OUT AS INDICATED	
	CLEAN PAINT FROM FLOOR AS INDICATED. TOUCH UP CHIP TO FLOOR AT TOP OF STAIRS. AND	
	AT DOOR JAM TO 3RD BEDROOM.	
MASTER ENSUITE BATH		
FAUCETS/PLUMBING	INSTALL FAUCETS TO TUB	
BASEMENT		
STAIRS	PAINT STAIRS	
EXTERIOR SEASONAL		
NOTE:	PAINT LINTELS	
	FINISH / PARGE FOUNDATION WALL AT SOUTH WINDOW	
	REMOVE PLASTIC FROM WEST FACING BASEMENT WINDOWS	
	PAINT TOUCH UPS TO FRONT DOORS	
	REMOVE EXCESS CONCRETE UNDER SOFFIT LEFT SIDE OF PORCH	
	INSTALL STEP AT LAUNDRY ROOM DOOR TO GARAGE	
BRICKS	BRICK WALL UNEVEN ON NORTH SIDE	
FAMILY ROOM		
FLOORING	FLOORBOARD DISCOLOURED	
FOYER/HALL		
FLOORING	CLEAN EXCESS GLUE FROM BEVELED JOINT	

Enrollment:

Purchaser Name: Thi KIM ANH NGUYEN

Thi KIM ANH NGUYEN

Phone Res: (416) 909-2652
Phone Bus: (416) 909-6466
Closing Date: June 22, 2021
Inspector: Chris Bergman

Orwel

Vendor / Builder: 39348

Project: Lormel Developments (Bradford) Ltd

Lot / Phase: 102 / 2 Plan: 51M-1087

Address: 271 Chelsea Crescent

Municiaplity: Town of Bradford West Gwillimbury **Inspection Date:** June 15, 2021

Page 2 of 2

THE	COMPLETED PRE	-DEL	_IVEF	RY IN	ISPEC	CTION	IS A FO	ORMAL	RECO	RD OF	F TH	E HOM	E'S C	ONDITIO	ON BEFORE	E THE	PURCH	ASER	TAKES	S POS	SSESS	ION IT	T WIL	L BE	USED.	AS
A RE	FERENCE FOR FL	JTUF	RE WA	ARR/	YTNA	REQU	ESTS.																			

* Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to sign this form on their behalf.

I have inspected my new home and I agree that the description of the items listed on this form are accurate.

Thi KIM ANH NGUYEN

Thi KIM ANH NGUYEN

Purchaser's Name (print)

Purchaser's Name (print)

Purchaser's Signature

Chris Bergman

Designate's Name (print)

Designate's Signature

Kas

Purchaser's Signature

Inspector's Name (print)

Inspector's Signature

Date (YYYY/MM/DD)

2021/06/15

June 15, 2021