



**Pratt Hansen Group**  
**Customer Service**  
**Phone: (705) 792-3883**  
**Fax: (705) 792-3893**

## Work Order

**Address:** 58 William Paddison Drive - Apt: 401 - Barrie  
**Location:** Cheltenham Estates - Phase: CHE - Lot: 23  
**Today's Date:** 28Mar11  
**Contact Name(s):** Nadirali Prasla and 308 Duckworth St.  
**Contact Phone No.:** Res: Bus: Bus2: Cell: (705) 770-0001  
**Company:** Barrie Carpet & Hardwood Centre  
**Attention:**  
**Telephone:** (705) 721-8555  
**Fax:** (705) 734-0005

**Please Complete the following items:**

Deficiency Number	Issue		Appt. Date/Time	Notes
4847	FOYER/HALL-FLOORING-CARPET GAPS BETWEEN TRIM AT CORNERS OF TRANSITION TO FOYER CERAMIC			
4848	FAMILY ROOM-FLOORING-CARPET GAP UNDER TRIM TO RIGHT HALF WALL AT ENTRY TO KITCHEN. PURCHASER IS CONCERNED THAT LIP IS TOO HIGH AROUND FIRPLACE MARBLE HEARTH. LIP ON TRANSITION TO KITCHEN, HALL TO KITCHEN AND HALL TO FOYER ALL HIGH.			
5106	Family Room- lip on transition to kitchen, hall to kitchen and hall to foyer all high			
5107	Foyer- carpet gap under trim to right of half wall at entry to kitchen			
5108	Family Room- lip is too high around fireplace marble			

	hearth			
--	--------	--	--	--

Date Completed: \_\_\_\_\_ Homeowner Signature: \_\_\_\_\_

Please schedule service to complete the work described above within two weeks of receipt of this Work Order. It is your responsibility to book your own appointment unless we have included appointment details on this form.

Your Service Person must ask the homeowner to sign this form when the work has been completed. If the owner is not available to sign this Work Order, the person who completes the work should sign and date the form. Fax the completed Work Order to us at 705-735-6991.

In the event that you do not complete this service work within 14 days, Pratt Homes reserves the right to carry out the repairs on your behalf and the labour and material costs may be billed back to you plus a 15% administrative fee.