

PDI Page 1 of 1



rage i oi i

Vendor/Builder#

34234

Purchaser Name : Phone Res:

Phone Bus: Closing Date :

Inspector:

Model Home

0000-00-00 Bruno Tidd Enrollment# Legal Address: Project: 1630990 DLS[19] Praff Hansen Group

Plan #:

Lot / Phase #: Municlapility: 5035 / CHS

Inspection Date: 13 Sep 2010

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition.

Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

- DAMAGED, INCOMPLETE OR MISSING
 Windows, side lights and other glazing. Window and door screens
- Bathtub sinks and toilets

- Bathroom accessories if provided
 Mirrors, counter tips and cabinetry
 Flooring (hardwood, vinyl, coramic tiles, carpeting)
 Interior finished and trien carpentry
- Furnace
- Hot water heater, if provided (not rental)
 Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors including garage overhead doors, door locks
- Faucets: Kitchen, bathroom, laundry room
 Exhaust fans (kitchen, bathrooms) if provided
 Electrical outlets and fixtures

- Gas fireplaces, incl.circulation fans, if provided
 Heat Recovery Ventilation system, if provided
- Heating system
 Hot water heater, if provided (not routal)
- Air conditioning system, if provided and if conditions permit

Also list here anything that can't l	be assessed horsuse for example is dirty or inaccessible.		
GENERAL COMMENTS			
INSPECTION START TIME	INSPECTION STARTED AT 7:PM ** PURCHASER HAS A NEW PHONE NUMBER -416-7053009		
NOTE:	APPLIACES WERE REMOVED, DISHWASHER NOT HOOKED ALL AREAS TO BE PATCHED AND REPAINTED THROUGHOUT NAIL HOLES SCOFF MARKS EVERYWHERE STORAGE ROOM PAS NO POWER		<u>-</u> -
MASTER BEDROOM			
TRIM	CLOSET VALANCE OUT CROOKED ROUGH EDGE REMOVE WINDOW COVERINGS		
ELECTRICAL/LIGHTING	LIGHT BOLE BURNT OUT		
UPPER HALL			•
WALLS	PAINT TOUCH UP ATTIC HATCH		
BEDROOM 2 ENSUITE	····		
WALLS	PAINT TOUCH OP REQUIRED WINDOW COVERINGS TO BE REMOVED IN ALL BEDROOMS		
BEDROOM#3			
WALLS	PAINT TOUCH OF REQUIRED TO LEFT OF CLOSET SMALL DARK SPOTS		
TRIM	DOOR STICKS		
MAIN BATHROOM			
-	CEILING FAR DOESN'T SEEM TO BE TRKING IN AIR		
STAIRS			
TRAEDS	ROUGH FINISH CARPET AT TWO BOTTOM STAIRS. SIDE FECING LIVING ROOM		
DINING ROOM			
WALLS	TOUCH UP SECURE CELING VENT OVER WINDOW		
CARDEN/PATIO DOORS	<u> </u>		
NOTE:	DOES NOT LOCK, SCREEN MISSING. FRAME BROKEN AT TOP OS SOLID BOOR		
KITCHEN	TRANSITION PIEC		
CABINETS	OPPER CABINET STICKS ON CEILING ABOVE SINK DOTTED		
POWDER ROOM			
ELECTRICAL/LIGHTIN	2 BULSS MISSIING		
LAUNDRY ROOM	<u> </u>		
NOTE:	FAN IN LAWDRY BLOWS OUT AIR DRYER VENT		
EXTERIOR		. –	
-	DECK RAIL LOSE NOT SECURED TO WALL ON RIGHT SIDE		

THE COMPUTER BOT DELINEAR AND STREET, A PARTIE AND STREET	
THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES	
POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS	
* Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they profide written authority to the vendor/built	der
authorizing the designate to sign this form on their behalf.	_
The state of the s	
Builder Representative Purchaser	
remon representative	

Designate's Signature

Designate's Name(please print) I the homeowner, confirm that all repair work listed has been completed

Purchaser

Lange 13 2010

31001-PDIF-01,01

RECEIVED