Lot# 5036 CHS 15 Cheltenham Rd Unit 2



FEB 1 7 2009

**Pre-Delivery Inspection Form** 

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any "substitutions" of items referred to in, or to be selected under, the Agreement of Purchase and Sale (APS), Please initial all changes and deletions, As a minimum check the following:

## • Windows, side lights and other glazing. Window and door screens • Bathtubs, sinks and toilets • Bathroom accessories, it provided • Mirrors, countertops and cabinetry • Flooring (hardwood, vinyl, ceramic tiles, carpeting) • Interior finishes and trim carpentry • Windows, interior and exterior doors (including garage overhead door). Door locks • Faucets: kitchen, bathroom, laundry room • Exhaust fans (kitchen, bathrooms), if provided • Electrical outlets and fixtures • Gas fireplaces, incl. circulation fans, if provided

Furnace
Heat Recovery Ventilation system, if provided
Heating system
Heating system
Hot water heater, if provided (not a rental)

Air conditioning system, if provided and if conditions permit

Comments

complete

Item #	Room/Location	Description
	BE WINDOW	BLOKEN TOP LEFT WINDOW NEXT TO SLIDER
2	LAUNDRY	DOOR SWINGS IN, IMPEDING OPENATION
	,	OF FRUNT LOAD INASHER
3	POWDER RM	PATCH TO LEFT OF G.F. I PLUG
4	KITCHEN	COUNTER TO RIGHT SIDE OF FRIDGE
5	LITCHEN	DOORS SHOW GAPS IN RETWEEN SIDE?
6	FURNAUE	ROOM THRE LOUSE AND, FLUOR NOT
		SELURE
1	PAINT	TOUCH UPS THATOUGHOST
8	CABLE + PU.	ONE GOVERS NOT INSTALLED
9	WIND ONS	CRANKS AND SCREWS, PATCH UNDER
		LIVING ROUMFUINDOW
10	MASTON BORN	HOLE IN FLOOR HEXT TO YOUT TO
		LEFT OF WINDRY
11	CLOSETT	DOORS AND SHELVING
12	KITCHEN	SCRATCHED AND HETTIL NICKS IN UPPERS
		TO KIGHT OF STOVE
13	HYDL WATO	NOT INSTALLED
	OAI	
		·