PDI Prim Form Lage 1 of 1



PDJ Page 1 of 1



Vendor/Builder#

Phone Bus:

Purchaser Name: Phone Res :

34234 Holon Recyle (705) 722-4829

Closing Date: 2011-06-24 Brumo Tidd Inspectora

Enrollment#

Legal Address: Project: Plaa #:

Lot / Phase #: Municiaplity:

DES[19] Praff Hanson Group

3010 / ESV

Inspection Date: 20 Aug 2011

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition.

Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other gluzing. Window and door screens
- Bathtub sinks and toilets

- Bathroom accessories if provided
 Mirrors, counter tops and cabinetry
 Flooring (bardwood, vinyl, ceramic tiles, carpeting)


- · Interior finished and trim carpentry

OPERATING CONDITION

- Windows, interior and exterior doors including garage overhead doors, door
- Faucets: Kitchen, bathroom, laundry room
 Exhaust fans (kitchen, bathrooms) if provided
 Electrical outlets and fixtures

- Gas fireplaces, including fans, if provided
 Heat Recovery Ventilation system, if provided
- Heating system.
- Hot water heater, if provided (not rental)
 Air conditioning system, if provided and if conditions permit

 Interior finished and frim carpentry Furnace Hot water heater, if provided (not rental) Exterior finished, driveways, walkways, decks and landscaping 		 Heating system Hot water heater, if provided (not rental) Air conditioning system, if provided and if conditions permit 		
	be assessed because for example is dirty or inacco	ssibic.		
GENERAL COMMENTS	<u>-</u>			
INSPECTION START TIME	INSPECTION STARTED AT INSPECTION PURCHASER HAS A NEW PHONE NUMBER 705-733-4408			
MASTER BEDROOM				
WALLS	orywail repairs where mark&o			
TRIM	DOOR TO WALK IN CLOSET STICKS OF	N FLOOR		
BEDROOM #2				
TRIM	BASEBOARD CHIP IN BASEBOARD NEAR	R ENTRY DOOR.		
MAIN BATHROOM				
WALLS	TOUCH OF ON CEILING OVER TUB EN	CLOSURE		
FOYER/HALL				
WALLS	PAINT NOT COMPLETE IN BOTH LIVE	N AND BROOM CLOSET.		
TRIM	DOOR TO BROOM CLOSET SCRAPES ON	CARPET.		



THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RE POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE V * Purchasers on owners who intend to designate someone to conduct the leathorizing the designate to sign this form on their behalf. Builder Representative	WARRANTY REQUESTS	
Hullier Representative	Lan Charach	
Designate's Name(please print) I the homeowner, confirm that all repair work listed has been completed.	Dosignate's Signature	
	Purchaser	Date
	i didiasa	