Page 1 of 1



PDĮ Page 1 of 1



Vendor/Builder#

Purchaser Name: Phone Res :

Krystyna Bourne (705) 721-929[

Phone Bus : Closing Date: Inspector:

2011-11-25 Bruno Tida Enrollment# Legal Address: Project:

DLS[19] Pratt Hansen Group

Plan#: Lot / Phase #: 3012 / ESV

Municlaphty:

Inspection Date: 14 Nov 2011

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition.

Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:


DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
 Flooring (handwood, vinyl, ceramic tiles, carpeting)
 Jutarior finished and trim carpentry

OPERATING CONDITION

- Windows, interior and exterior doors including garage overhead doors, door locks
- Faucets: Kitchen, bathroom, laundry room
 Exhaust fans (kitchen, bathrooms) if provided
- Electrical outlets and fixtures
 Gas fireplaces, incl. circulation fans, if provided
 Heat Recovery Ventilation system, if provided
- · Heating system
- · Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit $_{\rm g}$

 Hot water heater, if provided (not rental)
 Exterior finished, driveways, walkways, decks and landscaping Also list here anything that can't be assessed because for example is dirry or inaccessible. GENERAL COMMENTS INSPECTION START TIME INSPECTION STARTED AT 8:30 P.M. NOTE: DRYWALL REPAIRS REQUIRED THROUGHOUT WHERE MARKED. BEDROOM #2 WINDOWS operable window sodeaks when opened. MAIN BATHROOM DRYWALL REPAIRS WHERE MARKED ALL OVER CRILING. ROUGH finisees. FOYER/HALL DRYMALL REPAIRS WHERE MARKED IN LINER CLOSET TAPE SEPARATING FROM WALL BEHIND INTERIOR TRIM. WALLS LIVING ROOM ELECTRICAL/LIGHTING COVER PLATES CROOKED IN MOST OF LIVING ROOM PAINT REQUIRED ON END OF BULKHEAD FACING LIVING ROOM KITCHEN DRYWALL REPAIRS WHERE MARKED CEILING HAS LARGE CRACK WALLS IN CEILING. PURCHASER CONCERNED.



THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOMES CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS * Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to sign this form on their behalf.		
Builder Representative	Lytyne Beens	
Designate's Name(please print) I the homeowner, confirm that all repair work listed has been completed	Designate's Signature	
	Purchaser	Date