
PDI Print Form



## PDI Page 1 of 1





Vendor/Builder#

Purchaser Name:

Elizabeth Marshall and Robert Paul

Phone Res: Phone Bus :

Closing Date : Inspector: Bruno Tidd

2013-04-30

Legal Address: Project: Plan #:

Lot / Phase #: Municiaplity:

Enrollment#

DLS[19] Pratt Hansen Group

43405 / Building43

Inspertion Date: 23 Apr 2013

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition.

Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

Windows, side lights and other glazing. Window and door screens

Bathtub sinks and toilets

- Bathroom accessories if provided

Mirrors, counter tops and cabinetry
 Flooring (hardwood, vinyl, ceramic tiles, carpeting)
 Interior finished and trim carpetity

Hot water heater, if provided (not rental)
 Exterior finished, driveways, watkways, decks and landscaping

OPERATING CONDITION

Windows, interior and exterior doors including garage overhead doors, door

Faucers: Kitchen, bathroom, laundry room
 Bxhaust fans (kitchen, bathrooms) if provided
 Electrical outlets and fixtures

Electrical outlets and traums
 Gas fireplaces, incl.circulation fans, if provided
 Heat Rocoverry Ventilation system, if provided
 Heating system
 Hot water healer, if provided (not rental)
 Air conditioning system, if provided and if conditions permit

Also list here anything that can't b	be assessed because for example is dirty or inaccessible.		
GENERAL COMMENTS			
INSPECTION START TIME	INSPECTION STARTED AT 8:00 P.M.		
NOTE:	TOUCH UPS REQUIRED THROUGH OUT AS INDICATED. REMOVE EMPTY GROUT BAGS FROM BEHIND LAUNDRY ROOM DOOR.		
BEDROOM #2			
TRIM	NO TRIM IN CLOSET.		
MAIN BATHROOM			
FLOORING	GROUT SPOTS ON FLOOR AROUND TUB		
LIVING ROOM			
FLOORING	SEAMS IN LAMINATE ARE CAKED WITH WHITE SUBSTANCE IN SCHE AREAS COULD BE PAINT OR DESPAIL DUST.		<u> </u>
KITCHEN	<u> </u>		
CABINETS	LOWER TO LEFT OF BANK OF DRAWERS SCRATCHEED.		<del></del>
COUNTERTOPS	GLUE ON COUNTERTOP IN SEVERAL AREAS		
EXTERIOR			
DECK	CLEAN WHITE SUBSTANCE OFF DECK	-	

RECEIVED APR 2 5 2013 Man-4340S

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL REPOSSESSION IT WILL BE USED AS A REFERENCE FOR FITURE V* Purchasers or owners who intend to designate someone to conduct the I authorizing the designate to sign this form on their behalf.  Buildet Representative	NARRANTY RECHESTS	
Designate's Name(please print) I the homeowner, confirm that all repair work listed has been completed	Designate's Signature  Purchaser	- Dabe

31001-PD1F-01.01