PDI Print Form



## PDI Page 1 of 1



Vendor/Builder#

Purchaser Name: Phone Res:

Catherine Lentine

Phone Bus:

(705) 792-9616

2013-05-21 Closing Date: Bruno Tidd Inspector:

Enrollment#

845612 DLS[19] Pratt Hansen Group Legal Address:

Project: Plan #: Lot / Phase #: Municiaplity:

43410 / Building43

Inspection Date: 15 May 2013

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition.

Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

· Windows, side lights and other glazing. Window and door screens

· Bathtub sinks and toilets

Bathroom accessories if provided
 Mirrors, counter tops and cabinetry

Flooring (hardwood, vinyl, ceramic tiles, carpeting)
 Interior finished and trim carpentry

Hot water heater, if provided (not rental)
 Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

Windows, interior and exterior doors including garage overhead doors, door

locks

Faucets: Kitchen, bathroom, laundry room
 Exhaust fans (kitchen, bathrooms) if provided
 Electrical outlets and fixtures

Gas fireplaces, incl. circulation fans, if provided
 Heat Recovery Ventilation system, if provided

Heating system
 Hot water heater, if provided (not rental)

· Air conditioning system, if provided and if conditions permit

Also list here anything that can't be assessed because for example is dirty or inaccessible.

GENERAL COMMENTS		
INSPECTION START TIME NOTE:	INSPECTION STARTED AT 8:00 P.M.  ** PURCHASER HAS A NEW PHONE NUMBER - 705-792-9616 TGWO SCREWS MISSING ON ELECTRICAL PANEL. TOUCH UPS REQUIRED THROUGH OUT AS INDICATED	
MASTER ENSUITE BATH		
VANITY CABINETS	KNOB MISSING ON BOTH DOORS	
MAIN BATHROOM		
FAUCETS/PLUMBING	HOT AND COLD REVERSED IN SHOWER STALL	
VANITY CABINETS	KNOB MISSING ON BOTH DOORS	
KITCHEN		
CABINETS	UNDER MOUNT VALANCE TO BE ATTACHED UNDER UPPERS TO RIGHT OF STOVE.	
EXTERIOR		
NOTE:	LARGE CRACK IN CORNER SEAM LEDGE TO RIGHT OF EXTERIOR LIGHT	

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL REPOSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE *Purchasers or owners who intend to designate someone to conduct the authorizing the designate to sign this form on their behalf.	WARRANTY REOUESTS	
Phosp Builder Representative	Cathorish	ento.
Designate's Name(please print)  I the homeowner, confirm that all repair work listed has been completed	Designate's Signature	
	Purchaser	Date

31001-PDIF-01.01

