Lot 102 (MWI) 2114 NEVILS ST.

Comments DOURS TRUMBLE



12/16/2 Due /2

Pre-Delivery Inspection Form FEB 0 9 2009

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any "substitutions" of items referred to in, or to be selected under, the Agreement of Purchase and Sale (APS), Please initial all changes and deletions, As a minimum check the following:

DAMAGED, INCOMPLETE OR MISSING **OPERATING CONDITION** · Windows, interior and exterior doors (including garage overhead · Windows, side lights and other glazing. Window and door screens door). Door locks · Bathtubs, sinks and toilets · Bathroom accessories, it provided · Faucets: kitchen, bathroom, laundry room · Exhaust fans (kitchen, bathrooms), if provided · Mirrors, countertops and cabinetry · Electrical outlets and fixtures • Flooring (hardwood, vinyl, ceramic tiles, carpeting) · Gas fireplaces, incl. circulation fans, if provided · Interior finishes and trim carpentry · Heat Recovery Ventilation system, if provided Heating system · Hot water heater, if provided (not a rental) · Exterior finishes, driveways, walkways, decks and languscaping are · Hot water heater, if provided (not a rental) · Air conditioning system, if provided and if conditions permit complete

Room/Location GRADING, SOO DONED ONUTWAY EXTE 210R STEPS, DECK, BRUKWERK, PHINNING, ABTRUCK MUBING FAZIA SOFFITS, BALGSTROPHYS DWNSPOUTS, MUNIAPA MOORES RAINNE, SIWS COMPLESED THERTOR TRIM NOT COMPLOTE. 3 SNISH PLUMBING & KNISH ALEGIELUR NOT COMPACTE 1MENRUL NO CAMPETS, VANITIES of COUNDERDAS. TNASHUR SUBBRS, SPECIES & MIRROR NO-INSTILLED ROUNES NOT COMPLETED TOUR UPS TYPRO-614 OF BATTALOOMS COLLO NOT BE INSPECTED. DOOR HARDWARE NOT INSMILLED O\ THERE VENT COVERS MAY MOTITUDE NOT CUDYNEDO NO ELECTRONIA NO WOODS, NO BOT WATER NO SURCENS & WINDOW CKÁNKS INTELLOR - TOUCH UPS & BAPPING NEEDED CLARK IN BOSINAS WITTER & RAMPNESS IN ZOUGRAL MAME BLOKEN (SOUTH SINE MINS TO BASINETT DUY WAL KEILING MEDERCE - NOT CONPUTE ON IMEYOZ TO UCIT-UPS THROUGHOST MIL, PRYMAN, From & SMIS IN MER BROKER SOUTH WEST CORMER METER CHERGOR, 70

102 MWF. ST. 2174 WORLS ST.

Comments.

ONHW-PDIF-01.01





Pre-Delivery Inspection Form

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any "substitutions" of items referred to in, or to be selected under, the Agreement of Purchase and Sale (APS), Please initial all changes and deletions, As a minimum check the following:

DAMAGED, INCOMPLETE OR MISSING	OPERATING CONDITION
 Windows, side lights and other glazing. Window and door screens Bathtubs, sinks and toilets Bathroom accessories, it provided Mirrors, countertops and cabinetry Flooring (hardwood, vinyl, ceramic tiles, carpeting) Interior finishes and trim carpentry Furnace Hot water heater, if provided (not a rental) Exterior finishes, driveways, walkways, decks and landscaping are complete 	Windows, interior and exterior doors (including garage overhead door). Door locks Faucets: kitchen, bathroom, laundry room Exhaust fans (kitchen, bathrooms), if provided Electrical outlets and fixtures Gas fireplaces, incl. circulation fans, if provided Heat Recovery Ventilation system, if provided Heating system Hot water heater, if provided (not a rental) Air conditioning system, if provided and if conditions permit

Item #	Room/Location	Description		
26	POYER	CUSTOMER WAS CONCERN OVER MANSSTON		
		BETWEEN VINIGLE CARPES.		
27	earlyn65	MS- STAINEN		
$\mathcal{V}_{\mathcal{E}}$	IMEMUR	SURANS CHOWING ADUE ODDWAYS.		
29	MAN BORDM.	DEVISED IN/UMPEL CARPET		
30	MANWBUSHLIDM			
	MANTUOR	PRINTIPA KANSWICH LUCATION?		
32	WIRDAN	enacus ABUT BOTH ENTINES (BOTH SIDES)		
33	IMERIOR	TOUCH -UPS THEBUBH -COT.		
34	LOWER HAY	CHACK IN COUNT O EDGE FROM CLOSES.		
		Chief fire Country (C. Country (C. Country)		

Date	(CONT.).	Lot #	Unit Enrolment #