

Lot 46
1410 RANKIN WAY



JUL 28 2008

Pre-Delivery Inspection Form

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any "substitutions" of items referred to in, or to be selected under, the Agreement of Purchase and Sale (APS). Please initial all changes and deletions. As a minimum check the following:

DAMAGED, INCOMPLETE OR MISSING	OPERATING CONDITION
<ul style="list-style-type: none"> Windows, side lights and other glazing. Window and door screens Bathtubs, sinks and toilets Bathroom accessories, if provided Mirrors, countertops and cabinetry Flooring (hardwood, vinyl, ceramic tiles, carpeting) Interior finishes and trim carpentry Furnace Hot water heater, if provided (not a rental) Exterior finishes, driveways, walkways, decks and landscaping are complete 	<ul style="list-style-type: none"> Windows, interior and exterior doors (including garage overhead door). Door locks Faucets: kitchen, bathroom, laundry room Exhaust fans (kitchen, bathrooms), if provided Electrical outlets and fixtures Gas fireplaces, incl. circulation fans, if provided Heat Recovery Ventilation system, if provided Heating system Hot water heater, if provided (not a rental) Air conditioning system, if provided and if conditions permit

Comments Douglas Trumble Douglas

Item #	Room/Location	Description
1	INTERIOR	TOUCH-UPS THROUGHOUT.
2.	GARAGE	MAN DOOR VERY HARD TO OPEN/CLOSE.
3	POWDER ROOM	VANITY DOORS NEED ADJUSTMENT
4	INTERIOR	MIRRORS MISSING THROUGHOUT.
5	KITCHEN	DOORS UNDER SINK NOT INSTALLED
6	W.I.C.	ACCESS PANEL TO TUB NEEDS TO BE ATTACHED.
7	ENSURE.	MAR ON SHOWER BASE. / SHOWER DOOR NEEDS ADJUSTMENT.
8	ENSUITE.	CAPILLUM NEEDED @ TRIM
9	ENSUITE	VANITY DOOR DOESN'T SIT. / NO MIRROR
10	UPSTAIRS	CLOTHES CLOSET DOOR NEEDS DOOR SOFT.
11	MASTER BEDROOM. SINK AS MARKED.	
12	BEDROOM #3	3 MARKS ON CARPET (AS MARKED)
13	FRONT PORCH	SOFFITS/FACIA NEEDS TRIM @ FRONT EDGE
14	DINING ROOM SLIDERS	MISSING SCREEN
15	KITCHEN	HOOD FAN NEEDS TO BE INSTALLED
16	KITCHEN	AREA UNDER RAISED BAR - NEEDS TRIM/OR CUSHIONS
17	STAIRS TO BASEMENT. LANDING SHOWS -	- AND PAINTING. - WATER MARK ON HARDWOOD.
18.	SINK TO BASEMENT	PAINTING NEEDED, ON DOOR AS WELL.
19	BASEMENT	NO SCREENS ON WINDOWS
20	BASEMENT.	VENT COVER MISSING @ BASE OF STAIRS.
21	UPPER STAIRS	NEED CLEANING / DOOR NEEDS ADJUSTMENT
22	UPPER STAIRS	SWITCH FOR WHAT?
23	BASEMENT,	All VENTS MISSING
24	BASEMENT	LIGHT MISSING ABOVE SINK / MIRROR MISSING @ SINK.
25	BASEMENT BATH	DOOR WON'T SHUT.
25	UTILITY ROOM.	NEEDS CLEANING
26.	BASEMENT BATH.	TOILET PAPER DISPENSER TO BE ATTACHED.
27	KITCHEN	COUNTERTOP DAMAGED ON LEFT SIDE OF SINK.
28	GARAGE DOORS	RIGHT SIDE HAS MARK (ODM.)
29	GARAGE (MAN DOOR)	DENT ON SIDE FACING GARAGE.