

PDI Page 1 of 1



Vendor/Builder#

Purchaser Name:

Alana Brown and Chris Currie

Phone Res: Phone Bus: Closing Date: Inspector:

(705) 321-8666

2013-08-15 Bruno Tidd

Enrollment# Legal Address: Project:

Municiaplity:

Plan #:

locks

DLS[19] H Hansen Development Inc

SWD-00001 / 1

• Faucets: Kitchen, bathroom, laundry room • Exhaust fans (kitchen, bathrooms) if provided

· Gas fireplaces, incl.circulation fans, if provided · Heat Recovery Ventilation system, if provided

Windows, interior and exterior doors including garage overhead doors, door

Inspection Date: 14 Aug 2013

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition.

Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

- DAMAGED, INCOMPLETE OR MISSING

 · Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets

- Hot water heater, if provided (not rental)
 Exterior finished, driveways, walkways, decks and landscaping
- Bathroom accessories if provided
 Mirrors, counter tops and cabinetry
 Flooring (hardwood, vinyl, ceramic tiles, carpeting)
 Interior finished and trim carpentry

OPERATING CONDITION

· Electrical outlets and fixtures

Heating system
Hot water heater, if provided (not rental)
Air conditioning system, if provided and if conditions permit

Also list here anything that can't be assessed because for example is dirty or inaccessible.

GENERAL COMMENTS			
INSPECTION START TIME	INSPECTION STARTED AT 8:15 P.M.		
NOTE:	TOUCH UPS REQUIRED THROUGH OUT AS INDICATED		
NEW TELEPHONE NUMBER	705-321-8666		
UPPER HALL			
NOTE:	CLOSET DOOR STICKS AT BOTTOM AND RUBS ON TRANSITION PIECE AT TOP OF STAIRS.		
MAIN BATHROOM			
VANITY CABINETS	LEFT DOOR HINGE LOOSE AT TOP.		
STAIRS		<u>, </u>	***
-	ROUGH DRYWALL FINISH WHERE CARPET MEETS STAIRS GAPS ETC.		
KITCHEN			
CABINETS	UPPER CABINET IN CORNER TO RIGHT OF SINK LOOSE AT TOP HINGE.		
ELECTRICAL/LIGHTING	PHONE JACK IS BEHIND STOVE, NOT FUNCTIONAL.		

I the homeowner, confirm that all repair work listed has been completed		
Designate's Name(please print)	Designate's Signature	
Builder Representative	Purchaser	
* Purchasers or owners who intend to designate someone to conduct the authorizing the designate/to sign this form on their behalf.	PDI in their place should ensure the	ey provide written authority to the vendor/builder
lam	WARRANTY REQUESTS	

31001-PDIF-01.01

