

## PDI Page 1 of 1



Vendor/Builder#

Purchaser Name:

Keri Coad and Dan Fontaine

Phone Res: Phone Bus:

(705) 792-4260

Closing Date: Inspector:

2013-06-17 Bruno Tidd Enrollment#

Legal Address:

Project: Plan #: Lot / Phase #: Municiaplity:

DLS[19] H Hansen Development Inc.

SWD-00065 / 1

Inspection Date: 10 Jun 2013

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition.

Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

## DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- Bathroom accessories if provided
   Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
   Interior finished and trim carpentry

- · Hot water heater, if provided (not rental)

OPERATING CONDITION

Windows, interior and exterior doors including garage overhead doors, door locks

Faucets: Kitchen, bathroom, laundry room

· Exhaust fans (kitchen, bathrooms) if provided · Electrical outlets and fixtures

Gas fireplaces, incl.circulation fans, if provided
 Heat Recovery Ventilation system, if provided

Heating systemHot water heater, if provided (not rental)

· Air conditioning system, if provided and if conditions permit

· Exterior finished, driveways, walkways, decks and landscaping Also list here anything that can't be assessed because for example is dirty or inaccessible. GENERAL COMMENTS INSPECTION START TIME INSPECTION STARTED AT 6:00 P.M. PLEASE PAINT TRIM STOP ON ALL UPSTAIRS CLOSETS. TOUCH UPS REQUIRED THROUGH OUT AS INDICATED NOTE: NEW TELEPHONE NUMBER 705-792-4260 SHARED ENSUITE DOOR FROM MASTER TO ENSUITE DOES NOT CLOSE PROPERLY TRIM STAIRS CARPET FINISH UNDER STAIR RISER IN LIVING ROOM WRAPS CARPET RUNNER FOYER/HALL HEAT VENT COVER DOES NOT SIT FLUSH FLOORING KITCHEN VENT COVER NEAR STAIRS DOES NOT FIT. FLOORING POWDER ROOM PAINT OCTAGON WINDOW TRIM. TRIM FINISHED BASEMENT DOOR TO WASHROOM AND DOOR TO STORAGE UNDER STAIRS DO NOT CLOSE. SCREENS MISSING IN BASEMENT WINDOWS. VENT NOTE: IN WASHROOM CEILING NOT FLUSH.DRYWALL TO LEFT OF SATIRS BEHIND DOOR HAS LARGE GAP. REQUIRES TRIM PIECE LIKE THE ONE ON THE RIGHT SIDE.

| THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL REPOSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE V.* Purchasers or owners who intend to designate someone to conduct the authorizing the designate to sign this form on their behalf. | WARRANTY REOUESTS     |      |
|---|-----------------------|------|
| Builder Representative  |                       |      |
| Designate's Name(please print)  | Designate's Signature |      |
| I the homeowner, confirm that all repair work listed has been completed   |                       |      |
|   |                       |      |
|   | Purchaser             | Date |

31001-PDIF-01.01

