rage 1 of 1



PDI Page 1 of 1

TARION 3300

Vendor/Builder#

Purchaser Name: Phone Res:

Omar Dixon (905) 874-9985

Phone Bus: Closing Date : Inspector: 2013-07-25

Bruno Tidd

Enrollment# Legal Address: Project:

DLS[19] H Hansen Development Inc.

Lot / Ph Municiaplity:

Plan #:

SWD-00080 / I

Inspection Date: 17 Jul 2013

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition.

Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

· Windows, side lights and other glazing. Window and door screens

- Bathrub sinks and toilets
 Bathroom accessories if provided
 Mirrors, counter tops and cabinetry
 Flooring (hardwood, vinyl, ceramic tiles, carpeting)
 Interior finished and trim carpentry
 Furnace
- · Furnace
- Hot water heater, if provided (not rental)
 Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- · Windows, interior and exterior doors including garage overhead doors, door locks
- · Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- Electrical outlets and fixtures
 Gas fireplaces, incl. circulation fans, if provided
- · Heat Recovery Ventilation system, if provided
- Heating system
 Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

Also list here anything that can't be assessed because for example is dirty or inaccessible

GENERAL COMMENTS		
INSPECTION START TIME NOTE:	INSPECTION STARTED AT 10 10 A.M. TOUCH UPS REQUIRED THROUGH OUT AS INDICATED. SCRRENS MISSING IN BASEMENT WINDOWS.	
BEDROOM #2	AISSING IN BASEMENI WINDOWS.	
WALLS	ACCENT WALL SHOULD BE WIPED DOWN. VERY DUSTY,	
STAIRS		 = 7411
RAILING	ROUGH FINISH	
LIVING ROOM		
WALLS	LEFT CORNER WALL APPEARS CROOKED SLATING DOWNWARDS.	
BASEMENT		
NOTE:	FLOOR HAS EXTREMELY ROUGHUNDER THE STAIRS	

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS * Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to sign this form on their behalf. Builder Representative Designate's Name(please print) Designate's Signature I the homeowner, confirm that all repair work listed has been completed Purchaser

31001-PDIF-01.01

