



PDI  
Page 1 of 1



Vendor/Builder #  
Purchaser Name : Raul Cano and Robin Lesperance  
Phone Res : (705) 503-1993  
Phone Bus :  
Closing Date : 2013-03-25  
Inspector: Bruno Tidd

Enrollment #  
Legal Address: DLS[19]  
Project: H Hansen Development Inc.  
Plan #:  
Lot / Phase #: SWD-00084 / 1  
Municipality:

Inspection Date: 23 Mar 2013

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

#### DAMAGED, INCOMPLETE OR MISSING

• Windows, side lights and other glazing. Window and door screens

• Bathtub sinks and toilets  
• Bathroom accessories if provided  
• Mirrors, counter tops and cabinetry  
• Flooring (hardwood, vinyl, ceramic tiles, carpeting)  
• Interior finished and trim carpentry  
• Furnace  
• Hot water heater, if provided (not rental)  
• Exterior finished, driveways, walkways, decks and landscaping

#### OPERATING CONDITION

• Windows, interior and exterior doors including garage overhead doors, door locks  
• Faucets; Kitchen, bathroom, laundry room  
• Exhaust fans (kitchen, bathrooms) if provided  
• Electrical outlets and fixtures  
• Gas fireplaces, incl. circulation fans, if provided  
• Heat Recovery Ventilation system, if provided  
• Heating system  
• Hot water heater, if provided (not rental)  
• Air conditioning system, if provided and if conditions permit

Also list here anything that can't be assessed because for example is dirty or inaccessible.

#### GENERAL COMMENTS

INSPECTION START TIME INSPECTION STARTED AT 5:35 homeowners new number is 705 503 1993. ALL SCREENS ARE MISSING. CENTRAL AIR IS NOT INSTALLED. EXTERIOR FINISHES TO BE COMPLETED.

#### MASTER BEDROOM

• TOUCH UP PAINT IN CLOSET ON CORNER BEAD.

#### BEDROOM #2

• CRACKED TRIM IN CORNER OF ROOM ON FLOOR TO THE RIGHT OF WINDOW. CEILING NEEDS REPAIR. WINDOW FRAME IS SCRATCHED.

#### BEDROOM #3

• STAIN ON CARPET BY DOORWAY

#### MAIN BATHROOM


• PAINT REQUIRED ON BATHROOM DOOR FROM HALL.

#### FOYER/HALL

• FRONT CLOSET DOORS SHOULD BE MIRRORED DOORS. DRYWALL REPAIRS WHERE MARKED

#### POWDER ROOM

• PAINT TOUCHUPS



THIS COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS

\* Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designee to sign this form on their behalf.

Builder Representative

Purchaser

Designate's Name (please print)

Designate's Signature

I the homeowner, confirm that all repair work listed has been completed

Purchaser

13/23/03  
Date