



Pratt Hansen Group Group Inc. Phone: (705) 792-3883

Fax: (705) 792-3893

Address: 41 Coulter St Unit 13 - Barrie

Sunnidale Vistas - Phase: SUN - Lot: 2013 Location:

Today's Date: 18Apr11

Contact Name(s): Olga Tyran and Julia Pavkovic

Contact Phone No.: Res: (705) 487-1924 Bus: (705) 487-2313 Bus2: (705) 309-5858 Cell: (705) 717-0549

Company: **North York Tile** Attention: Sebastian Spatola Telephone: (905) 660-7684 Fax: (905) 660-7687

Please Complete the following items:

Date Completed: _____

Deficiency Number	Issue	Appt. Date/Time	Notes
5252	Main Bathroom- towel rod has broken from wall		

Homeowner Signature: _

Please schedule service to complete the work described above within two weeks of receipt of this Work Order. It is your responsibility to book your own appointment unless we have included appointment details on this form.

Your Service Person must ask the homeowner to sign this form when the work has been completed. If the owner is not available to sign this Work Order, the person who completes the work should sign and date the form. Fax the completed Work Order to us at 705-735-6991.

In the event that you do not complete this service work within 14 days, Pratt Homes reserves the right to carry out the repairs on your behalf and the labour and material costs may be billed back to you plus a 15% administrative fee.