



Pratt Hansen Group
Customer Service
Phone: (705) 792-3883
Fax: (705) 792-3893

Work Order

Address: 43 Coulter St Unit 25 - Barrie
Location: Sunnidale Vistas - Phase: SUN - Lot: 3025
Today's Date: 21Jun10
Contact Name(s): Teresa Monteleone and Antonio Monteleone
Contact Phone No.: Res: (705) 792-4491 Bus: Bus2: Cell:
Company: North York Tile
Attention: Sebastian Spatola
Telephone:
Fax: (905) 660-7687

Please Complete the following items:

Deficiency Number	Issue		Appt. Date/Time	Notes
2177	LAUNDRY ROOM-FLOORING-CERAMIC TILE RAISED 3RD TILE IN FROM DOOR			

Date Completed: _____ Homeowner Signature: _____

Please schedule service to complete the work described above within two weeks of receipt of this Work Order. It is your responsibility to book your own appointment unless we have included appointment details on this form.

Your Service Person must ask the homeowner to sign this form when the work has been completed. If the owner is not available to sign this Work Order, the person who completes the work should sign and date the form. Fax the completed Work Order to us at 705-735-6991.

In the event that you do not complete this service work within 14 days, Pratt Homes reserves the right to carry out the repairs on your behalf and the labour and material costs may be billed back to you plus a 15% administrative fee.