

## PDI Page 1 of 1



Vender/Builder#

Purchaser Name : Phone Res :

34234

Phone Bus :

431--607*\$* 431--607*\$* 

Closing Date:

Doug Trumble

Enrollmeat# Legal Address: Project: Plan #:

DLS[19] Pratt Hansen Group

Municiaplity:

152 / WP1

Inspection Date: 21 Apr 2019

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition.

Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS).

Please initial all changes and deletions As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- · Windows, side lights and other glazing. Window and door screens
- Bathtub sinks and toilets

- Bathroom accessories if provided
   Mirrors, counter tops and cabinetry
   Pluoring (hardwood, vinyl, ceramic tiles, carpeting)
   Jutorior finished and trim carpetary

OPERATING CONDITION

- · Windows, interior and exterior doors including garage overhead doors, door locks
- Fauncts: Kitchen, bathroom, laundry room
   Exhaust fans (kitchen, bathrooms) if provided

- Electrical outlets and fixtures
   Gas freplaces, incl.circulation fans, if provided
   Heat Recovery Ventilation system, if provided


- Heating system
   Hot water heater, if provided (not cental)
   Air conditioning system, if provided and if conditions permit

Hot ware heater, if provided (not rental)

Exterior finished, driveways, walkways, decks and landscaping

Also list here anything that can't be assessed because for example is dirty or inaccessible.

MASILE MASILIE DATE		
TOILET	CRACKED on front edge-as marked	
BEDROOM#3		
-	caulking requested on edges of attick hatch	
MAIN BATTIROOM	•	
-	linen closet doorstop to be removed- non functional- door hits towel rack	 
KTTCHEN X		
-	CABINETS- base corner-sink base- no blind corner CABINETS- drawer back very skinny customer not happy with oclour variation between drawers finished end CHIPPED in several areas.	 <u> </u>
EXTERIOR		
-	man door in garage needs paint due to patches elbow/screen missing on power vent shigle to be trimmed/tucked in to rear left corner customer nothappy with stepsafety hazard, foot catching agreen missing on rear right window customer concerned about dead treeNOT on property but would plausibly fall on fence and deck.	 
EXTERIOR SEASONAL		
•	PAINT not completed driveay, grading, sod - not completed.	 
GARAGE DOORS	left door look needs adjustment- will not latch if shuttingfrom outside	 
NOTE:	lot number sprayed onto foundation- will be visable after finished quade	 



THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL REPOSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE V* Purchasers or owners who intend to designate someone to conduct the authorizing the designate to sign this form on their behalf.  Builtin Representative	WARRANTY REQUESTS	:
Designate's Namo(please print)  1 the homeowner, confirm that all repair work tisted has been completed	Designate's Signature	
	Purchaser	Date

31001-PDIF-01.01