107 157 (WPI) 51.



RECEIVED

AUG 17 2009

LUCITISTICATE

Form

**Pre-Delivery Inspection Form** 

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any "substitutions" of items referred to in, or to be selected under, the Agreement of Purchase and Sale (APS), Please initial all changes and deletions, As a minimum check the following:

## DAMAGED, INCOMPLETE OR MISSING **OPERATING CONDITION** · Windows, side lights and other glazing. Window and door screens · Windows, interior and exterior doors (including garage overhead · Bathtubs, sinks and toilets door). Door locks · Bathroom accessories, it provided · Faucets: kitchen, bathroom, laundry room · Mirrors, countertops and cabinetry · Exhaust fans (kitchen, bathrooms), if provided · Flooring (hardwood, vinyl, ceramic tiles, carpeting) Electrical outlets and fixtures · Interior finishes and trim carpentry • Gas fireplaces, incl. circulation fans, if provided Furnace • Heat Recovery Ventilation system, if provided · Hot water heater, if provided (not a rental) Heating system • Exterior finishes, driveways, walkways, decks and landscaping are · Hot water heater, if provided (not a rental) complete • Air conditioning system, if provided and if conditions permit

Comments DUD WS MW3L Room/Location EXTERIOR PAVED PRIVEWAY INCOMPLETE. EXTERIOR NEVENTER STRIPPING EXTERNA COACH LIGHT UNISSING TOP WALKWAY 1110 STONE CRAIKED CHARGED UNDBLLEST COALL CHE UGHT of Home OPNIS & SURMINES INDOWS NOT SELVEE ABJUE INSMUED CRACKED ADDER DENTS BROW WINDOW VERY DIKKLUT TO GERME CONLEANED TRANSITION THIM IN BE SELVICED WWD WEE TER NOT INS Unit Enrolment # 163 6952 1 ONHW-PDIF-01.01

LOT # 15



Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any "substitutions" of items referred to in, or to be selected under, the Agreement of Purchase and Sale (APS), Please initial all changes and deletions, As a minimum check the following:

## DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtubs, sinks and toilets
- · Bathroom accessories, it provided
- · Mirrors, countertops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- · Interior finishes and trim carpentry
- Hot water heater, if provided (not a rental)
- · Exterior finishes, driveways, walkways, decks and landscaping are complete

## **OPERATING CONDITION**

- Windows, interior and exterior doors (including garage overhead door). Door locks
- · Faucets: kitchen, bathroom, laundry room
- · Exhaust fans (kitchen, bathrooms), if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl. circulation fans, if provided
- · Heat Recovery Ventilation system, if provided
- Heating system
- · Hot water heater, if provided (not a rental)
- · Air conditioning system, if provided and if conditions permit

Commen	its WALAS TO	vmice flagget
Item #	Room/Location	Description
29	KIRHAN	WITOMER COMERNESS THE COMPLETOR MITTLE
		VEALLE (VERY VISABLE).
30	KIRMEN/6020	PENELL (VERY VISABLE).  ROM WITCHER LONGENED ARM TRANSITU  BETWEEN CENTUL & WILDWOOD NOT
	& PSWOON.	BETWEEN CERMIL & HALDWAY - NOT
		ARN NOT FLUSH
31	LANDM	DOR DIGHLUT TO DREW.  PT. DOR MICSING LIFE HANDE
32	6ARA, F	RT DON MISSING LIFT HANDLE
_		
•		
-		