10T 181 1232 LAURAND



Pre-Delivery Inspection Form

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any "substitutions" of items referred to in, or to be selected under, the Agreement of Purchase and Sale (APS), Please initial all changes and deletions, As a minimum check the following:

DAMAGED, INCOMPLETE OR MISSING	OPERATING CONDITION	
Windows, side lights and other glazing. Window and door screens Bathtubs, sinks and toilets Bathroom accessories, it provided Mirrors, countertops and cabinetry Flooring (hardwood, vinyl, ceramic tiles, carpeting) Interior finishes and trim carpentry Furnace Hot water heater, if provided (not a rental) Exterior finishes, driveways, walkways, decks and landscaping are complete Comments WWW Comments	Windows, interior and exterior doors (including garage overhead door). Door locks Faucets: kitchen, bathroom, laundry room Exhaust fans (kitchen, bathrooms), if provided Electrical outlets and fixtures Gas fireplaces, incl. circulation fans, if provided Heat Recovery Ventilation system, if provided Heating system Hot water heater, if provided (not a rental) Air conditioning system, if provided and if conditions permit	

Item #	Room/Location	Description
/	EXTERIOR	BACK HOSE BIBB LEAKING
2.	EXT. ELECTRICAL	RECEPTIONS NOT INSTALLED IN SUFFET
		ASPER (APS).
3.	EXTERIOR	VENT COUR NOT SEUDED (WEST SOFFIT).
4.	EXTENIOR	ORMANY NOT PARO.
5	DUWNYDUT3	MISSING ABUS(X2)
6	200 From	OUBLIDE OF WINDUS CIRTY
7	MISTER BEDGEO	U. OVER SPRAN ENGE OF WAIL TO CETUME
		(AS MARKED)
8	BABMENT	WINDOW DUESN'T WARE - (OPEN PROPERLY).
	(SOUTH-EMST)	WINDL CAP NOT SECURED.
9	BASEMENT	WEST WALL WINDOW - SIDE HARES NOT ATTERED
/D	RAILMES TO BAR	
1/	REM SUDER	SCROON DIFFICULT TO OPPRITE AND ARE
12	WANDOW	(RIGHT SIDE OF KINERAGE) - GAP @CASING
		AS MARKED.
13	LAVNDRY	COVER MEDER FOR ALARM ROLLY-IN.
		DEARINER
		RECEIVED
		NOV 0 9 2009
		WPI-181