



Pratt
HOMES

Pre-Delivery Inspection Form

DAMAGED, INCOMPLETE OR MISSING	OPERATING CONDITION
• Windows, side lights and other glazing. Window and door screens • Bathtubs, sinks and toilets • Bathroom accessories, if provided • Mirrors, countertops and cabinetry • Flooring (hardwood, vinyl, ceramic tiles, carpeting) • Interior finishes and trim carpentry • Furnace • Hot water heater, if provided (not a rental) • Exterior finishes, driveways, walkways, decks and landscaping are complete	• Windows, interior and exterior doors (including garage overhead door). Door locks • Faucets: kitchen, bathroom, laundry room • Exhaust fans (kitchen, bathrooms), if provided • Electrical outlets and fixtures • Gas fireplaces, incl. circulation fans, if provided • Heat Recovery Ventilation system, if provided • Heating system • Hot water heater, if provided (not a rental) • Air conditioning system, if provided and if conditions permit

DOUBIAS TRIMBLE. *Doyle*

ONHW-PDIF-01.01

Date**Lot #**

Unit Enrolment \$

1625323

1

1914 SWAN ST.