

210-1455 Youville Drive Ottawa, On K1C 6Z7 Phone: 613-837-1104

Vendor:

DALMEN PRODUCTS LTD 5630 ST-CATHERINE STREET **PO BOX 220**

ST-ISIDORE, ONTARIO K0C 2B0

tel:

613-524-2268

fax: contact:

MARC BELLEFEUILLE info@dalmen.com

Ship To:

Site:

PLACE ST. THOMAS PHASE 7

Lot/Unit:

LOT 15

Model: Civic:

1030

934 COLOGNE STREET

ORDER DATE Feb 02, 2024	CHG. ORDER DT.	CANCEL DATE	RESPONSIBILITY ARIEL	VENDOR # D33	TERMS NET 60 DAYS	
Comments/Special Instructions:					REFERENCE	
				*		

JOB/LOT/COST	REFERENCE	Description	QTY ORDERED	UNIT PRIC	E EXTENSION
-	1130-0000	REPLACE BROKEN WINDOW FRONT PORCH ATTCHED INVOICE #994-27379	1.0000	560,1900	560.19
		-	= - a		
	4				
			,		
					2
			=		
			Subtotal		560.19
	1 Som		HST		72.82

ORDER TERMS AND CONDITIONS

- 1. INVOICES must bear exact same prices and terms or authorization for changes must be received from our company in writing prior to shipping. The right is reserved to cancel all or part of this order if not delivered within the time specified.

Authorized Signature

- 3. Packing slips must accompany all shipments. 4. In the event of interruption of our business in whole or in part by reason of fire, flood, windstorm,earthquake, war, strike, embargo, acts of God, governmental action, or any causes beyond our control, we shall have the option of cancelling undelivered orders in whole or in part.
- 5. Acceptance of this pirchase order, or shipment of it will constitute an agreement to all of its specifications as to terms, delivery and prices.
- 6. No deliveries accepted after 4:00 pm or on weekends.

Total Order Value

633.01

FIELD REQUEST FORM 2023 Work Order: □ theck Purchase Order: ☐ Gheck Notice Of Back Charge: □ theck Trade: DALMEN WINDOWS Lot/Unit: LOT 15 Project Site : PST-7 Date Issued: JAN 31 Description of Work or Material Being Ordered: Amount: REPLACE BROKEN WINDOW FRONT PORCH LOT Reason & Cause Due To for Work Being Done or Material Ordered: DAMAGED BY SUB FOR BYTOWN *** Note: Reason & Cause information Mandatory for Purchase Orders*** Total Amount Cost Responsibility: **Construction Damage** Errors Internal: Check Vandalism Damage: ☐ Check (Not being Back Charged) Check Trade Related Damage: Check ☐ Check Theft: Reported to Police Yes: Check Police Department: Police Report: Police Occurrence No.: Back Charge To: 13470WW MASONRY Notification Given To: VINCE ARCOTTA Date Notified Trade: JAN 30 /24 Notice Given By: JUSTIN STOLL Repair Work Preformed By: DALMEN Note (1): Should you wish to deal directly with the repair contractor, he must issue written confirmation to Valecraft Homes Ltd that he has received Payment. Note (2): Contractor acknowledges that unless contested, the aforementioned amount's back charged will be deducted off your next cheque. Site Foreman Approval:

Const. Manager Approval:



Quotation

JOB: LOT 15 PH7 934 COLOGNE ST

SOLD TO:

VALECRAFT HOMES (2019) LTD VALECRAFT HOMES (2019) LTD

1455 YOUVILLE DRIVE

SUITE 210

ORLEANS ONT.

K1C 6Z7

Telephone: (613)837-1104

SHIP TO:

VALECRAFT HOMES LTD VALECRAFT HOMES LTD 1455 YOUVILLE DRIVE

SUITE 210

ORLEANS ONT.

K1C 6Z7

ID: 994-27379

2024-01-30

2024-01-30 2024-02-20

CREATED:

Date required:

LAST MODIFICATION:

ITEM	QTY	CODE	TYPE OF PRODUCT	UNIT NET PRICE
1	1	GLASS	Replacement Thermos (1094 mm x 1689 mm)	385.19 \$
1.	43 1/8 ' Frame	Dou mm 66 1/2 " 7/8" == No Dal	CTANGULAR DALMEN uble Double Thermo Lowe Climaguard Super Spacer Black 80/71 4 ' (0.875) 22mm TOTAL THICKNESS Dalumex Service No Warranty == Warranty umex	

				TOTAL:	385.19 \$
ITEM	QTY	CODE	TYPE OF PRODUCT		UNIT NET PRICE
2	1		SERVICE CHARGE (GLASS REPLACEMENT)		175.00 \$
├ F	" rame	" 		fat.	
				TOTAL:	175.00 \$

ID:

994-27379

Customer:			
Salesman:		SUB-TOTAL:	560.19 \$
	Service Department		
Date:		HST (13%) :	72.82 \$
Date	The state of the s	N/A (0%) :	0.00 \$
	Terms and conditions:	TOTAL:	633.01 \$
	NET 30 JOURS	10174	033.01 ψ
тніѕ	S QUOTATION IS VALID FOR 30 DAYS		

Purchase Orders

From:

Justin Stoll

Sent:

Wednesday, January 31, 2024 2:44 PM

To:

Purchase Orders

Cc:

varlotta@bytownmasonry.com

Subject:

LOT 15 Field Request/Notice of back charge

Attachments:

attachment 1.pdf; LOT 15 PH 7.pdf

Hi Ariel,

Can you write up a po for Dalmen to replace broken window at lot 15? Vince from Bytown was notified of back charge Jan 30/24 and is copied on this email.

See quote from Dalmen and field request below.

Justin Stoll

Site Supervisor Valecraft 2019 Embrun 613-809-2654