

NEWMAR WINDOW MFG. INC. ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6 TEL (905) 672-1233 FAX (905) 672-1076

WO # W134583

Service Date: Aug 16, 2021

Priority:	Normal	Status:	SCHEDULED		RELEASED	
BUILDER						
Customer:	611313	City:	INNISFIL	Received:	Apr 29, 2021	
Name:	ZANCOR BELLE AIRE SHORES	Service Phone(s):		Time:	1ST CALL	
Service Fax:		Site Phone:		Order:	D364348-1	
Site Fax:		Lot#:	7	Phase:		

RESIDENT INFORMATION

1528 ANJUS Home Owner Name: JOANNE, M OSTROWSKI Address:

Home Phone(s): 905-251-5850 Work Phone(s):

Cell Phone(s): Email(s): joanne.ostrowski@gmail.com

LINKED ORDER INFORMATION

611313 ZANCOR BELLE AIRE SHORES Lot #: Customer: 7

Model: 50-07 DELTA ST+OP GF(LOFT)/WH Phase:

SERVICE INSTRUCTIONS

OTHER- GENERAL ADJUST GMD.

FOYER- GENERAL- FRONT DOOR EXTREMELY HARD TO CLOSE, DOES NOT CLOSE WITHOUT FORCING DOOR SHUT ADD

EXTERIOR- GENERAL DECORATIVE TRIM OVER LEFT GARAGE DOOR NOT THE SAME AT RIGHT SIDE

ADD:

1 SERVICE TO ADD STD AG GRILLES TO LINES 30, 40, 100, 110, 120, 130

PARTS REQUIRED		71	lo Signed	Buck wp	
LN Item Description	Location	Specification	Size	Options	Qty
171 5' 8" CLAD DOOR SYS 22 X 48 cutout	ENT	SLABS-OPERATIN G FOR DOUBLE DRS	70.5 X 81.75	RIGHT STEEL 200_SERIES TYPE1 WH	1
201 NEWMAR VINYL CASEMENT FIXED	LOFT	GLASS ONLY - FIXED	15.75 X 42.75	AG24 WH LOWE_ARG WH	1
202 NEWMAR VINYL CASEMENT	LOFT	GLASS ONLY - SASH	15.75 X 42.75	AG24 WH LOWE_ARG WH	1
211 NEWMAR VINYL CASEMENT	LOFT	GLASS ONLY - SASH	15.75 X 42.75	AG24 WH LOWE_ARG WH	1
212 NEWMAR VINYL CASEMENT FIXED	LOFT	GLASS ONLY - FIXED	15.75 X 42.75	AG24 WH LOWE_ARG WH	1
270 NEWMAR VINYL CASEMENT	LFT/B2	GLASS ONLY - SASH	18.75 X 56.75	AG25 WH LOWE_ARG WH	1
280 NEWMAR VINYL CASEMENT FIXED	B2	GLASS ONLY - FIXED	18.75 X 56.75	AG25 WH LOWE_ARG WH	1
290 NEWMAR VINYL CASEMENT	LDY	GLASS ONLY - SASH	18.75 X 34.75	AG23 WH LOWE_ARG WH V	1
301 NEWMAR VINYL CASEMENT FIXED	LOFT/B3/B4	GLASS ONLY - FIXED	18.75 X 42.75	AG24 WH LOWE_ARG WH	1
302 NEWMAR VINYL CASEMENT FIXED	LOFT/B3/B4	GLASS ONLY - FIXED	18.75 X 42.75	AG24 WH LOWE_ARG WH	1
303 NEWMAR VINYL CASEMENT	LOFT/B3/B4	GLASS ONLY - SASH	18.75 X 42.75	AG24 WH LOWE_ARG WH	1

Problem Description:

Warranty Material \$	CHARGEABLES Material \$
Labour \$	Labour \$ P.O.#:
Cause:	
Solution:	
Date Completed: Aug 16/21	Approved:
Time: 22 hs	Service Signature:

						D364	1348-3 (Seq #4))					
		Т	YPE:	LA	TE E	XTRA D	ESCRIPTION:	S1	TATUS: SUBMIT	TED			
		7.77	ANGE									Date: Ju	uly 15, 2021
USTOMER No.		QUO	OTE N	э.		cus:	TOMER P.O. No.		LISTED WITH LOT			ORE	DER#
611313		E2	289953							V		D36	4348
BUILDER & S	ITE		Р	HASI	=	LOT No.	SITING		MODEL	Е	LEV.	SLS ID	CREATED BY
ANCOR BELLE AIRE	SHORE	S				7	REVERSED				D	0069	Eric Cigana
S: U TOP ONL	Y 🗀	AG [SERVIC AG21 AG-0	E TO INS	TALL (GRILLE C	OLOU	R: 🗌 WH	☐ 2-TONE
ROOM LOC'N	QTY	JOIN	N	CS MT	SLI DER		PRODUCT C	ODE DES	CRIPTION			PRICE / UNIT	TOTAL
								ADD					
	1					SERVICE TO A	DD STD AG GRILI	LES TO LI	NES 30, 40, 100, 1	10, 120, 1	30		
TER CHANGE EASE RODUCTION - ON SITE LACE - STOLEN DAMAGE	□ c □ c □ E	ODE 03 ODE 04 XTRA				OTHER (Specify)							0.00
	EXTRA TO JSTOMER No. 611313 BUILDER & S ANCOR BELLE AIRE SIDE SUPPLIER RE VBM S:	EXTRA TO CONTR USTOMER No. 611313 BUILDER & SITE ANCOR BELLE AIRE SHORE SIDE SUPPLIER REQ'N VBM S: TOP ONLY R DW SW ROOM QTY LOC'N 1 TER CHANGE EASE CRODUCTION CON SITE LACE - STOLEN COMMAGE CONTRIBET CONTRIBET CONTRIBET	NEWMAR EXTRA TO CONTRACT / CH JSTOMER No. QU 611313 E2 BUILDER & SITE ANCOR BELLE AIRE SHORES SIDE SUPPLIER REQ'N VBM S:	NEWMAR EXTRA TO CONTRACT / CHANGE JSTOMER No. QUOTE No. 611313 E289953 BUILDER & SITE PANCOR BELLE AIRE SHORES SIDE SUPPLIER REQ'N VBM S: TOP ONLY AG HER NOW WHO IV ROOM QTY JOIN TER CHANGE EASE CODE 02 RODUCTION CODE 03 ON SITE CODE 04 LACE - STOLEN EXTRA DAMAGE OTHER	NEWMAR EXTRA TO CONTRACT / CHANGE JSTOMER No. QUOTE No. 611313 E289953 BUILDER & SITE PHASE ANCOR BELLE AIRE SHORES SIDE SUPPLIER REQ'N	EXTRA TO CONTRACT / CHANGE JSTOMER No. QUOTE No. 611313 E289953 BUILDER & SITE PHASE ANCOR BELLE AIRE SHORES SIDE SUPPLIER REQ'N VBM S: TOP ONLY AG HER HORIZ ROOM QTY JOIN CS SLI ROOM QTY JOIN CS SLI ROOM LOC'N MT DER TER CHANGE EASE CODE 02 RODUCTION CODE 03 ON SITE CODE 04 LACE - STOLEN EXTRA DAMAGE OTHER	NEWNAR EXTRA TO CONTRACT / CHANGE USTOMER No. QUOTE No. CUS 611313 E289953 BUILDER & SITE PHASE LOT No. ANCOR BELLE AIRE SHORES 7 SIDE SUPPLIER REQ'N VBM S: TOP ONLY AG HER HORIZ AG22 A ROOM QTY JOIN CS SLI MT DER TER CHANGE EASE CODE 02 RODUCTION CODE 03 ON SITE CODE 04 LACE - STOLEN EXTRA DAMAGE OTHER	TYPE: LATE EXTRA DESCRIPTION: NEWMAR EXTRA TO CONTRACT / CHANGE USTOMER No. QUOTE No. CUSTOMER P.O. No. 611313 E289953 BUILDER & SITE PHASE LOT No. SITING ANCOR BELLE AIRE SHORES 7 REVERSED SIDE SUPPLIER REQ'N CUSTOM SERVICE SERVICE TO PONLY AG HER HORIZ AG22 AG21 AG4-0 AG4-0 BY DER CUSTOM SERVICE SERVICE TO ADD STD AG GRILL TER CHANGE S	NEWMAR EXTRA TO CONTRACT / CHANGE USTOMER No. QUOTE No. CUSTOMER P.O. No. 611313 E289953 BUILDER & SITE PHASE LOT No. SITING ANCOR BELLE AIRE SHORES 7 REVERSED 50-0 SIDE SUPPLIER REQ'N CUSTOMER PICK SERVICE TO INS' S: TOP ONLY AG HER HORIZ AG22 AG21 AG-0 ROOM QTY JOIN CS SLI PRODUCT CODE DES LOC'N MT DER TER CHANGE EASE CODE 02 RODUCTION CODE 03 ON SITE CODE 04 LACE - STOLEN EXTRA DAMAGE OTHER	NEWMAR EXTRA TO CONTRACT / CHANGE USTOMER No. QUOTE No. CUSTOMER P.O. No. LISTED WITH LOT 611313 E289953 BUILDER & SITE PHASE LOT No. SITING MODEL ANCOR BELLE AIRE SHORES 7 REVERSED 50-07 DELTA ST+OP GF(LOFT)/WH SIDE SUPPLIER REQ'N CUSTOMER PICKUP SERVICE TO INSTALL SIDE SUPPLIER REQ'N AG21 AG-0 ROOM QTY JOIN CS SIL PRODUCT CODE DESCRIPTION 1 SERVICE TO ADD STD AG GRILLES TO LINES 30, 40, 100, 1 TER CHANGE EASE CODE 02 RODUCTION CODE 03 ON SITE CODE 04 LACE - STOLEN EXTRA DAMAGE OTHER	TYPE: LATE EXTRA DESCRIPTION: STATUS: SUBMITTED	TYPE: LATE EXTRA DESCRIPTION: STATUS: SUBMITTED	TYPE: LATE EXTRA DESCRIPTION: STATUS: SUBMITTED

Lisa Harvey | 07-15-2021 11:51 am

Page



Work Order

Closing Date:

17Dec20

Address:

Innisfil, ON

Location:

Belle Aire Shores - Phase: 1 - Lot: 7

Today's Date:

26Apr21

Contact(s):

Joanne, M Ostrowski - Home: (905) 251-5850

Email:

joanne.ostrowski@gmail.com

Company:

Newmar

Attention:

Alex

Telephone:

(905) 672-1233

Fax:

(905) 672-6350

Please Complete the following items:

DAI	Туре	Issue	Appt. Date/Time	Notes	
141907	Interval	Other- General- ADJUST GMD	09Apr21 /am	Arrival 8am-12pm	/
142903	30-Day	Foyer- General- Front door extremely hard to close. Does not close without forcing door shut	09Apr21 /am	Arrival 8am-12pm	ı

Date Completed: Aug 16/21.

Date Completed: Aug 16/21

Homeowner Signature: X

The Homeowner acknowledges and accepts all work has been completed in a workman like manner.

Trade &/or Service Tech.

Print Name: Steven

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

Failure to comply with this request within 10 business days will give Zancor Homes (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.



NEWMAR WINDOW MFG, INC. ALPA LUMBER GROUP

ALPA LUMBER GROUP

(20 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6
TEL (905) 672-1233 FAX (905) 672-1076

WO # W134583

Service Date: Jun 05, 2021

Priority: Normal	Status:	SCHEDULED		
BUILDER				
Customer: 611313	City:	INNISFIL	Received:	Apr 29, 2021
Name: ZANCOR BELLE AIRE SHORES	Service Phone(s)):	Time:	1ST CALL
Service Fax:	Site Phone:		Order:	D364348-1
Site Fax:	Lot#:	7	Phase:	
RESIDENT INFORMATION				
Home Owner Name: JOANNE, M OSTROWSKI	Address	S:		
Home Phone(s): 905-251-5850	Work P	hone(s):		
Cell Phone(s):	Email(s): joanne.ostrows	ki@gmail.com	
LINKED ORDER INFORMATION		ned		
Customer: 611313 ZANCOR BELLE AIRE SHORE	s wan	Lot #: 7		
Model: 50-07 DELTA ST+OP GF(LOFT)/WH	even to	Phase:		
SERVICE INSTRUCTIONS	No OK	1528 AL	9-02 C	2
OTHER- GENERAL ADJUST GMD.			~	
FOYER- GENERAL- FRONT DOOR EXTREMELY HA	ARD TO CLOSE, DOE	ES NOT CLOSE WITHOUT	FORCING DO	OR SHUT
Problem Description: 34 Zpanel	100	22 48 C	+ MI	
Problem Description: 5 t / 1944	TIFC	22/10 000	1 00	
Warranty	П СНА	ARGEABLES		
Material \$ 8	ٺ Materia			
Labour \$	Labour	\$		
	P.O.#:			
Cause:				
0.14				
Solution:				
A 2				
Date Completed: 5 6 2021	Ap	proved:		
-				
			Ana	
Time:	Service Sig	gnature:	STATE OF THE PARTY	
			ГНОЙҮ	10



Service Department <servicedept@newmar.com>

Fwd: Lot 7 Innisifl

1 message

Melissa Green <mgreen@newmar.com>

To: Service Department <servicedept@newmar.com>

Tue, Jun 15, 2021 at 8:18 AM

07.06.2021 alex

----- Forwarded message -----

From: Gisella Fiore < Gisella@zancorhomes.com>

Date: Mon, Jun 14, 2021 at 3:08 PM

Subject: Lot 7 Innisifl

To: service@newmar.com <service@newmar.com>

Good Afternoon

Any update below?

Deficiencies on Belle Aire Shores - 1 - 7 For Newmar

DAI	Туре	Issue	Appt. Date / Time	Notes
142903	30-Day	Foyer- General- Front door extremely hard to close. Does not close without forcing door shut	20May21 am	Arrival 8am- 12pm
141907	Interval	Other- General- ADJUST GMD	20May21 am	Arrival 8am- 12pm

Service Manager



Gisella Fiore

Gisella@zancorhomes.com

P: 905.738.7010 F: 905.738.5948

221 North Rivermede Road- Concord, ON L4K 3N7

CONFIDENTIALITY NOTICE: This email message, including any attachments, is for the sole use of the intended recipient(s) and may contain confidential and privileged information. Any unauthorized review, use, disclosure or distribution is prohibited. If you are not the Intended recipient, please reply to the sender by email and destroy all copies of the original message.

Please note that our response lead time is longer than before due to backlogs which we have in this pandemic. Thank you for your understanding and patience

Thank you 👵 Melissa Green **Customer Service Facilitator**