



**Zancor Homes (Cookstown) Ltd.**  
**Warranty Services**  
**Phone: (905) 738-7010**  
**Fax: (905) 738-5948**

**Work Order**

**Closing Date:** 07Aug20  
**Address:** 48 Mumberson St.  
Cookstown, Ontario  
**Location:** Cookstown - Phase: 1 - Lot: 3  
**Today's Date:** 26Jul21  
**Contact(s):** Lisa Lynn Goodey - Home: (416) 471-3195  
Andrew, James, Frederick Goodey -  
**Email:** lisa.goodey@snclavalin.com

**Company:** Medi Group  
**Attention:**  
**Telephone:** (416) 741-2737  
**Fax:** (416) 741-1593

**Please Complete the following items:**

DAI	Type	Issue		Appt. Date/Time	Notes
145224	Interval	Exterior- General- inspect cracks in window sill at back of house			

Date Completed: \_\_\_\_\_

Homeowner Signature: \_\_\_\_\_  
The Homeowner acknowledges and accepts all work  
has been completed in a workman like manner.

Date Completed: Aug. 19/21

**Trade &/or Service Tech.**

Signature: [Signature]

Print Name: Teresa Mari

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

**Failure to comply with this request within 10 business days will give Zancor Homes (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.**



# MEDI GROUP Service

WO Number : **W-077600**WO Date : **18-Aug-2021**Issued To : **GERALDO****Builder :** Zancor **ZAN08**  
**Project :** ZANCOR HOMES (COOKSTOWN) LTD.**Lot No :** 3  
**Model :** 5005 (A)**Directions :** Cookstown  
Intersection of Queen St (Hwy 89) and  
Dufferin St (south of Queen and west of**Address :**  
**Contact :****Main Brick :** Sierra Brown**Main Stone :****Accent Brick :****Accent Stone :** Ryegrass Renaissance

INIT	Item	Work Description	PO	Builder Ref #
	1	INSPECT CRACKS IN WINDOW SILL AT BACK OF HOUSE		3JUL2621
				S-061706

2 sills replaced

Special Notes :

\_\_\_\_\_  
Homeowner Signature\_\_\_\_\_  
Date Completed\_\_\_\_\_  
Site Super Signature\_\_\_\_\_  
Date Completed

Scanned

AUG 16 2021

Completed