

Zancor Homes (Innisfil) Ltd. Warranty Services

Phone: (905) 738-7010 Fax: (905) 738-5948



Hamsourner Cianoture



\cap		Data	40BA	0
O10:	sing	Date:	10May1	19

Address: 1002 Larter Street

Innisfil, Ontario

Location:

Belle Aire Shores - Phase: 2 - Lot: 77N

Today's Date:

30Aug21

Contact(s):

Ali Eshtiyaghi - Cell: (647) 528-2827

Email:

uoftali@gmail.com

Campani	 I I mi fui
Company	Uni-tri

Data Campleted

Attention:

Joey/Jason

Telephone:

(416) 745-2724

Fax:

(416) 745-1375

Please Complete the following items:

DAI	Туре	Issue	Appt. Date/Time	Notes
145723	Interval	Exterior- General- Inspect large gaps in masonry throughout		

Date Completed:	The Homeowner acknowledges and accepts all work has been completed in a workman like manner.
Date Completed: SEPT 28 2021	Trade &/or Service Tech.
	Signature: 74
	Print Name: VCat Right

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

Failure to comply with this request within 10 business days will give Zancor Homes (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

Uni-Tri Masonry (1989) Limited 23 Haas Road Etobicoke, ON M9W 3A1

Telephone: (416) 745-2724 Fax: (416) 745-1375

White: Office

WORK ORDER

12308

Pink: Site

EXTRA TO CONTRACT

Builder:	ZMCORE		
Project:	BGWAIRE SHORES		
Lot No.	PHA LOT 77N		
Address:	1002 LARTER STREET		
Builder Ref:	Description of Work To Be Completed	Description of Work Performed	Time
145723	- LARGE GAPS IN	- GRINDED SPLIT	
,	MASONRY THROUGHOUT	STONES TO SIZE	
	,	OF A JOINT AND	
	- MANY STONES WERE		
	NOT SPLIT AND NEVER	MORTAR	,
	GOT FILLED WITH	- WENT OVER STONE	
	MORTAR	SKIRT TO REAR OF HUNE	
		-LARLE BUMPOUT ON SIDE	=
		WALL	
		- FRONT WAS STONE UPT	0
		BOTTOM OF TOP FLOOR WIT	roows
		- COVERED ALL STONE AL	EAS
Chargeable To:		Total Hours	0
Date Complete	d: TUESDAY SEM 28 20	» /	
	Work Order, I agree to all the information provide for the work performed (labour) and/or (labour &		sonry
Superintendent	Signature:		
Serviceman Sig	gnature: 7/1		
	1		

Yellow: Service Department