

Zancor North Inc. Warranty Services Phone: (905) 738-7010 Fax: (905) 738-5948

Closine Date: 04Nov20

Work Order

Address: .ocation: Foday's Date Contact(s): Email:	Wasaga The Vill : 26Nov2' Steven, (simecha Lynn Go simecha	52 Blanca Crescent Wasaga Beach The Village of Trillium Forest - Phase: 3 - Lot: Block 134 Unit 2 26Nov21 Steven, J Goad - Home: (416) 717-9076 Cell: (416) 684-3041 - (sjmechanicalinc@gmail.com) Lynn Goad sjmechanicelinc@gmail.com								
Attention: Telephone:	(705) 42 (705) 42	8-6484								
DAI	Type	lssue		Appt. Date/Time	Notes					
146370	1 Year	Basement- General- Item #3- basement floor has a lot of cracking	/	29Nov21 /pm						
146383	Interval	Kitchen- General- Svc to fill gap at arch at entrance to kitchen at trim		29Nov21 /pm						
Date Comp	leted:	Nov 29/21	Homeowner Signature; The Homeowner acknowledge, and accepts all work has been completed in a workman like manner.							
Date Completed: 12/29/2/			Trade &/or Service Tech							
			Signatu	ire:						
			Print N	ame: XIDO	THE EN					
appointm adhere to	ent time or the appoir		nis form, ed. Your s	it is your resp service repre						

Failure to comply with this request within 10 business days will give Zancor Homes (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

page 2/2

Page 1 of 1

Outstanding Deficiencies The Village of Trillium Forest - Phase: 3 - Lot: Block 134 Unit 2

<u>Date</u> Reported	Туре	Number	Deficiency Description	Trade Assigned	Add Trade	Appointment Date	Item Completed	Initial
15Nov21	l Year	2	Stairs- General- Item #1- Hardwood gap between hardwood and stair	First Canadian Hardwood 146368	Add	29Nov21		
15Nov21	1 Year	3	Other- General- item #2- doors - inspect front door bowed and adjust	Newmar 146369	Add	29Nov21		
15Nov21	l Year	4	Basement- General- Item #3- basement floor has a lot of cracking	Wasaga Zancor Warranty Service 146370	Add	29Nov21	V	5.6
15Nov21	Interval	3	Kitchen- General- Svc to fill gap at arch at entrance to kitchen at trim	Wasaga Zancor Warranty Service 146383	Add	29Nov21	V	S.6.
15Nov21	Interval	4	Exterior- General- Inspect eaves left side of garage at valley leaking onto driveway, photo sent	Promark Aluminum LTD. 146384	Add	29Nov21		
15Nov21	Interval	5	Exterior- General- Inspect Missing downspout at back of house only one spout for both lots causing water to flow	Promark Aluminum LTD. 146385	<u>Add</u>	29Nov21		

Homeowner Signature:	
The Homeowner acknowledges and accepts that a nitialled work has been completed in a workman lil namer to their satisfaction.	
Date: Nov 29 /21 Zancor Service Technician: Service	

https://bstapps.com/zancor/data/builderforms/ZanHSReportDeficiencyCheckList.php?&v... 2021-11-26