Horday Micromber GOSFM - POWNER



Zancor Homes (Cookstown) Ltd. Warranty Services
Phone: (905) 738-7010

Work Order

Fax: (905) 738-5948

Closing Date:
Address:

Location:
Today's Date:
Contact(s):
Email:

30Nov20 40 Victoria St Cookstown, Ontario Cookstown - Phase: 1 - Lot: 29 03Dec21

Munice Wright - Home: (705) 220-1193 - (slewinwright@gmail.com) slewinwright@gmail.com

Zancor-Cookstown Service

Company:
Attention:

Telephone:

Please Complete the following items:

DAI	Туре	Issue	Appt. Date/Time	Notes
146399	1 Year	Basement- General- Item #1- copy of permit requirements	06Dec21 /am	
146406	1 Year	Basement- General- Item #8- cold cellar door installation does not provide an adequate weather seal or the door opening are not properly insulated	06Dec21 /am	
146411	1 Year	Main Bathroom- General- Item #13- cracks on trim in open room sunk in holes to be filled	06Dec21 Jam	
146414	1 Year	Main Bathroom- General- Item #16- all bathroom nail pop and cracks- mini suite hill in hole between cabinet and trim	06Dec21 /am	
146415	1 Year	Shared Bathroom- General- Item #17-	06Dec21 /am	

73 MAD

146430	146429	146428	146427	146425	146423	
1 Year	1 Year	1 Year	1 Year	1 Year	1 Year	
Bedroom 2- General- Item #27- all bedroom cracks to be sealed on 30 day told to wait until year end	Laundry Room- General- Item #26- settlement cracks to be sealed from 30 day told to wait until year end	Laundry Room- General- Item #25- settlement cracks	Main Hall- General- Item #24- was painted from 30 day but not done properly	Main Hall- General- Item #220 bedroom door frame piece is splitting from the bottom up, was painted over but can see the cracking running up the side of the door- FILL SAND PAINT	Bedroom 2- General- Item #20- all 4 rooms trim nails pop and fading painting, spots missed from 30 day(svc to touch up yellow stain behind dresser in master/ Master closet and window trim at bedroom above garage)	mini suite yellow on marble to clean up and bottom of shower needs more caulking on outside and rusting parts needs more glue or caulking
1	7	5				
06Dec21 /am	06Dec21	06Dec21	06Dec21 /am	06Dec21 /am	06Dec21 /am	
		1				

Stairs- General- Item #42- gap on right side not filled
Dining Room- General- Item #37- Touch up trim above archway at front door and at entrance to mud room. Stand on stairs can see ontop
Main Hall- General- Item #36- trim around both front side entrance doors missing paint spots on the top board, cracks and nail pops in floor trim
Kitchen- General- Item #33- heat vent missing screw from removed and put back
Kitchen- General- Item #32- caulking between tile cracked- from 30 day but told to wait for year
Main Bathroom- General- Item #30- needs caulking between shower and
Stairs- General- Item #29- nail pops, gap trim does not lay flat on stair landing
Stairs- General- Item #28- settlement cracks nail pops clean up where stair rail and wall meet

146468	146467	146459	146455	146454	146453	146452	146451	146450	146449
1 Year	1 Year	1 Year	1 Year	1 Year	1 Year	1 Year	1 Year	1 Year	1 Year
Exterior- General- Item #59 the seal around the man door from the	Exterior- General- Item #58- installation of the brick appears to be 7 below standard quuality.	Exterior- General- Item #52-cement under window around the house have cracks	Living Room- General- Item #51- celling- settlement cracks, nail pops (living room + dining room)	Other- General- Item #50 - furnace room- heat in house still unbalanced and not working properly- SVC CONDUCT INFRARED READING	Basement- General- Item #49- all windows cracks to be filled from 30 days	Basement- General- Item #48- bedroom doors- settlement cracks in door frame to be filled from 30 days	Basement- General- Item #47- bedroom closer- inside trim not secured above door	Bedroom 2- General- Item #46- caulking left on door from previous work to be cleared off	Bedroom 2- General- Item #45- register not secured
						7	7	1	1
06Dec21 /am	06Dec21 /am	06Dec21 /am	06Dec21 /am	06Dec21 /am	06Dec21 /am	06Dec21 /am	06Dec21 am	06Dec21 /am	06Dec21 /am

				_	
146474	146473	146472	146471	146470	
1 Year	1 Year	1 Year	1 Year	1 Year	
Bedroom 2- General- Item #65- door vinyl frame, the nail coverings are not	Bedroom 2- General- Item #64- caulking is required around the exterior light fixture	Exterior- General- Item #63- visible opening or holes in the garage ceiling and, or walls including light fixture receptacles or pipes leading to the building interior	Exterior- General- Item #62- missing handrail or guardrail is an unsafe condition- svc measure height	Exterior- General- Item #61- exterior fascia requires sealing around the joint openings to prevent water penetration's and air leakage- SVC TO CAULK BETWEEN BRICK AND FASCIA AT FRONT PORCH	house into the garage is damaged- SVC TO CAULK AROUND MAN DOOR AT ENTRANCE TO HOUSE FROM GARAGE
			7		
06Dec21 /am	06Dec21 /am	06Dec21 /am	06Dec21 /am	06Dec21 /am	

Date Completed: + Dec. 15"/21

Date Completed:

Homeowner Signature: X

The Homeowner acknowledges and accepts all work has been completed in a workman like manner.

Trade &/or Service Tech.

Signature: *

Print Name:

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

Failure to comply with this request within 10 business days will give Zancor Homes (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.