## Now Towns In Brooklin - Phase: 1 - Lot: Unit 14 (Block 2) **Outstanding Deficiencies**

		NoAppoint.	Add	Perfect Touch Painting 146819	Exterior- General- Painting not complete at exterior	13	PDI	25Feb22
	X	NoAppoint.	Add	Toronto Concrete & Drain 146818	Basement- General- Inspect ceiling in cold room. Light coming through	12	PDI	25Feb22
au.		NoAppoint.	Add	VIP Railings Inc. 146817	Stairs- General- x2 cracked newel post at main floor at stairs to powder room	11	PDI	25Feb22
an.		NoAppoint.	Add	MARCIANO DOORS AND TRIM 146813	Stairs- General- Gap at stringer and trim @ trim at first landing	7	PDI	25Feb22
an.		NoAppoint.	Add	MARCIANO DOORS AND TRIM 146812	Stairs- General- Missing trim at 8th trade right of stringer	6	PDI	25Feb22
		NoAppoint.	Add	New Image Kitchens 146811	Kitchen- General- Chip on lower left cabinet at sink	5	PDI	25Feb22
		NoAppoint.	Add	New Image Kitchens 146810	Kitchen- General- 2 Chip on left gable at electrical outlet and base	4	PDI	25Feb22
		NoAppoint.	Add	New Image Kitchens 146809	Kitchen- General- Chip on right island gable right of sink (Bottom)	ω	PDI	25Feb22
		NoAppoint.	Add	New Image Kitchens 146808	Kitchen- General- Chip on lower right garbage door left of sink	2	PDI	25Feb22
		NoAppoint.	Add	New Image Kitchens 146807	Kitchen- General- Chip on upper left cabinet left of stove	1	PDI	25Feb22
Initial	Item Completed	Appointment  Date	Add Trade	Trade Assigned	Deficiency Description	Number	Туре	<u>Date</u> <u>Reported</u>

Homeowner Signature:

The Homeowner acknowledges and accepts that all initialled work has been completed in a workman like manner to their satisfaction.

Date: 3/10/22
Zancor Service Technician: 72

NATHAN SIMAS



The items listed below were released to the homeowner(s) of

Purchaser	The above items were received on this/O day of	N/A Other	N/A Recycling and Green Bins	Homeowner Manual	House and Garage Door Keys	Lot # /9
Purchaser	of MARCH 2021					Site/Phase:_Brooklin