

CLOSES 3/31

Outstanding Deficiencies
Now Towns In Brooklin - Phase: 1 - Lot: Unit 9 (Block 2)

<u>Date Reported</u>	<u>Type</u>	<u>Number</u>	<u>Deficiency Description</u>	<u>Trade Assigned</u>	<u>Add Trade</u>	<u>Appointment Date</u>	<u>Item Completed</u>	<u>Initial</u>
17Mar22	PDI	1	EXTERIOR --PAINTING NOT COMPLETE	Perfect Touch Painting 146915	Add	NoAppointment		
17Mar22	PDI	2	MASTER BEDROOM- FLOORING-CARPET RAISED LEFT OF BALCONY DOOR	Zanco - Brooklin Warranty Service 146918	Add	NoAppointment	✓	V.P.
17Mar22	PDI	3	MASTER ENSUITE BATH- SHOWER ENCLOSURE-SMALL CHIP ON MARBLE SURROUND RIGHT OF GLASS AT LEDGE AND SMALL CHIP ON MARBLE SURROUND LEFT OF MIRROR	AV Classic 146916	Add	NoAppointment	✓	V.P.
17Mar22	PDI	4	MASTER ENSUITE BATH --SCRUFF ON LOWER LEFT CABINET BELOW LEFT SINK AND LOWER LEFT CABINET BELOW RIGHT SINK ABOVE HANDLE	New Image Kitchens 146917	Add	NoAppointment	✓	V.P.
17Mar22	PDI	5	BEDROOM 2 ENSUITE- COUNTERTOPS-SCRATCH ON COUNTERTOP RIGHT OF SINK	New Image Kitchens 146919	Add	NoAppointment	X	
17Mar22	PDI	6	BEDROOM #2- WINDOWS-CRACKED FIXED WINDOW LEFT SIDE	Newmar 146920	Add	NoAppointment		
17Mar22	PDI	7	KITCHEN- FLOORING-SMALL HOLE IN HARDWOOD LEFT OF ISLAND AND SMALL CHIP IN FRONT OF ISLAND FIRST PLANK	First Canadian Hardwood 146921	Add	NoAppointment	✓	V.P.
17Mar22	PDI	8	KITCHEN- FLOORING-SCRATCH ON HARDWOOD FLOOR IN FRONT OF STOVE 1 2 3 PLANK	First Canadian Hardwood 146922	Add	NoAppointment	X	
17Mar22	PDI	9	KITCHEN- CABINETS-CHIP INSIDE UPPER CABINET RIGHT GABLE AT SUVERY LEFT OF PANTY	New Image Kitchens 146923	Add	NoAppointment	✓	V.P.
17Mar22	PDI	10	KITCHEN- CABINETS-FILL NAIL HOLES ON ISLAND GABLE BOTH SIDES	New Image Kitchens 146924	Add	NoAppointment	✓	V.P.
17Mar22	PDI	11	KITCHEN- CABINETS-CHIP ON RIGHT ISLAND GABLE AT FLOOR	New Image Kitchens 146925	Add	NoAppointment	✓	V.P.
17Mar22	PDI	12	KITCHEN- CABINETS-CHIP ON RIGHT GABLE RIGHT OF STOVE	New Image Kitchens 146926	Add	NoAppointment	✓	V.P.
17Mar22	PDI	13	KITCHEN- CABINETS-CHIP INSIDE UPPER CABINET SHELF ABOVE FRIDGE	New Image Kitchens 146927	Add	NoAppointment	✓	V.P.
17Mar22	PDI	14	KITCHEN- CABINETS-INSPECT CRACK INSIDE UPPER LEFT GLASS CABINET BY GLASS INSERT AT HINGE CHIPPED	New Image Kitchens 146928	Add	NoAppointment	✓	V.P.

Homeowner Signature:

W. Kelly

The Homeowner acknowledges and accepts that all installed work has been completed in a workman like manner to their satisfaction.

Date: 3/31/22

Zanco Service Technician:

NT7H4U SIMAS