Enrollment:

Purchaser Name: Sheshank Bhanuri

Mounica Arugonda

Phone Res:

Phone Bus: (647) 972-3700
Closing Date: May 26, 2022
Inspector: Gisella Fiore

ZANCOR HOMES PDI

Page 1 of 2

selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

Vendor / Builder:

Project: Zancor Homes (Parkview) Ltd.

Lot / Phase: Unit 25 (Block 4) / 1

Plan: Address: Municiaplity:

Inspection Date: May 12, 2022

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

DINING ROOM		
WINDOWS	DAMAGED FIXED GLASS LEFT OF BALCONY DOOR 2) DAMAGED FIXED GLASS IN LIVING WINDOW LEFT OF OPERATING WINDOW	
KITCHEN		
CABINETS	UPPER BLACK CABINETS AS PER HOME OWNER SHOULD BE HIGH GLOSS BLACK	
WALLS	BACKSPLASH NOT INSTALLED	
MASTER BEDROOM		
FLOORING	REMOVE STAINS FROM CARPET AT ENTRANCE TO ENSUITE	
UPPER HALL		
FLOORING	CHIP ON 4TH HARDWOOD PLANK FROM LINEN ON CLOSET	
POWDER ROOM		
FLOORING	REMOVE SCRATCHES FROM 1ST 2ND AND 3RD TILE AT POWDER ROOOM	
	FLOOR VENT NOT FITTING FLOOR CUT TILE 1ST FLOOR POWDER ROOM	
LAUNDRY ROOM		
FLOORING	FLOOR CHIP ON PLANK AT ENTRANCE FROM MUD ROOM BY NOSING	
LIBRARY/DEN		
WINDOWS	ADJUST WINDOW LEFT OF BALCONY DOOR AND H.O REQUEST TO INSPECT THROUGHOUT	
FLOORING	CHIP ON 4TH AND 14TH PLANK FROM RIGHT WALL	
BASEMENT		
NOTE:	TRIM NOT COMPLETE AROUND BASEMENT COLD ROOM DOOR	
EXTERIOR		
GARAGE DOORS	NOT INSTALLED	
DECK	NOT INSTALLED	

Enrollment:

Purchaser Name: Sheshank Bhanuri

Mounica Arugonda

Phone Res:

 Phone Bus:
 (647) 972-3700

 Closing Date:
 May 26, 2022

 Inspector:
 Gisella Fiore



Vendor / Builder:

Project: Zancor Homes (Parkview) Ltd.

Lot / Phase: Unit 25 (Block 4) / 1

Plan: Address: Municiaplity:

Inspection Date: May 12, 2022

Page 2 of 2

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS.

* Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to sign this form on their behalf. I have inspected my new home and I agree that the description of the items listed on this form are accurate. Sheshank Bhanuri Mounica Arugonda Purchaser's Name (print) Purchaser's Signature Purchaser's Name (print) Purchaser's Signature Gisella Fiore Inspector's Name (print) Designate's Name (print) Designate's Signature Inspector's Signature May 12, 2022 Date (YYYY/MM/DD) 2022/05/12