Inspector: Gisella Flore	Closing Date: June 23, 2022	Phone Bus:	Phone Res:		Purchaser Name: Jasmine K Gill	Enrollment		
Gisella Flore	June 23, 2022	Phone Bus: (647) 470-5243		Navraj Singh Sidhu	Jasmine K Gill			
Page 1 of 2		į		1	ハイスつつス	- NOOD		
Inspection Date: May 31, 2022	Municiapilty:	Address:		CONTRACTOR OF THE PERSON NAMED IN COLUMN NAMED	Project: Zancor Homes (Caledon) Ltd.	Vendor / Builder:	/ /	June 23/2022

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of solected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the belowing:

- DAKAGED, INCOMPLETE OR MISSING

  Windows, side lights and delier glacing. Window and door screens

  Bathbod sints and toless

  Bathbod sints and toless

  Bathroom accessories if provided

  Mirrors, countor tops and cathretry

  Floring (heatwood, why, ceramic ties, carpeting)

  Interior finished and tim carpentry

  However heater, if provided (not mutal)

  Exterior finished, driewways, walkways, decks and landscaping

POYER/HALL STAIRS

- CABINETS

- OPERATING CONDITION

  Whitdows, history and exterior doors. Door bods
  Fauncis: Kitchen, bathroom, laundry room
  Eshausi fans (Nichen, bathrooms) if provided
  Electrical cultifor and houses
  Gas timplicas, incidentalistor fans, if provided
  Heat Recovery Vernitation system, if provided
  Heating system
  Hot water heater, if provided and if conditions permit

UPPER GABLE PEELING ABOVE FRIDGE SMALL CHIP ON 2ND TREAD AT STAIRS FROM 1ST L'ANDRIG TO 2ND FLOOR
BLACK STAIRS ON STH RISER AT STAIRS FROM MAIN FLOOR 2 FIRST L'ANDRIG TO 2ND FLOOR
GRACK ON STH TREAD BY PICKET AT STAIRS FROM MAIN FLOOR 2 FIRST L'ANDRIG TO 2ND
FLOOR