


NEWMAR WINDOW MFG. INC. ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6 TEL (905) 672-1233 FAX (905) 672-1076 WO # W160746 Pack Slip:202773

Service Date: Jul 20, 2022

170 NEWMAR VINYL CASEMENT B3 SCREENS-REPLA 25.0625 X CEMENT-WINDO 55.125 WS Problem Description: CHARGEABLES Material \$ Labour \$ P.O.#:	newmai	•		, , ,			
Customer: N000582	Priority:	Normal		Status:	SCHEDULED		
Name: ZANCOR BRAMPTON Service Phone(s): 416-791-9866 Time: D375521-1 Service Fax: Site Phone: 416-566-5475 Order: D375521-1 Stella Fax: Lott. 17 Phase: RESIDENT INFORMATION Home Owner Name: Address: Work Phone(s): Email(s): Email(s): LINKED ORDER INFORMATION (D375521-1) Customer: N000582 ZANCOR BRAMPTON Lot #: 17 Model: 36-5 / OPT.58 / RR.UPG (WOB) (CB) Phase: SERVICE INSTRUCTIONS FOYER/HALL - TRIM-DAMAGED DOOR TRIM MIDDLE: DAW MASTER ENSUITE BATH- TRIM-DAMAGED WINDOW MULLIN LEFT SIDE. LIVING ROOM GENERAL- ADJUST WINDOW IN LIVING ROOM PARTS REQUIRED LIN Item Description Location Specification Size Options day 170 NEWMAR VINYL CASEMENT B3 SCREENS-REDA 25.0625 X CEMENT-WINDO 55.125 Problem Description: CHARGEABLES Material S Labour \$ P.O.#: Date Completed: July January CHARGEABLES Material S Labour \$ P.O.#: Date Completed: July January Approved: Approved: January Approved: J	BUILDER						
Service Fax:	Customer:	N000582		City:	BRAMPTON	Received	May 30, 2022
Site Fax: Lot#: 17 Phase: RESIDENT INFORMATION Home Owner Name: Address: Home Phone(s): Work Phone(s): Cell Phone(s): Email(s): LINKED ORDER INFORMATION (D375521-1) Customer: N000582 ZANCOR BRAMPTON Lot #: 17 Model: 36-5 / OPT.58 / RR.UPG (WOB) (CB) Phase: SERVICE INSTRUCTIONS FOYER/HALL - TRIM-DAMAGED DOOR TRIM MIDDLE. COLUMBED AMONG AND AMORE A	Name:	ZANCOR BRAMPTON		Service Phone(s):	416-791-9866	Time:	
RESIDENT INFORMATION Home Owner Name:	Service Fax	:		Site Phone:	416-566-5475	Order:	D375521-1
Home Owner Name: Home Phone(s): Cell Phone(s): Email(s): LINKED ORDER INFORMATION (D375521-1) Customer: N000582 ZANCOR BRAMPTON Lot #: 17 Model: 36-57 OPT-587 / RR.UPG (WOB) (CB) Phase: SERVICE INSTRUCTIONS FOYER/HALL- TRIM-DAMAGED DOOR TRIM MIDDLE. BEDROOM #3- WINDOWS-WINDOW SCREEN BOWED BEDROOM RIGHT OF STAIRS WASTER ENSUITE BATH- TRIM-DAMAGED WINDOW MULLIN LEFT SIDE. LIVINO ROOM- GENERAL- ADJUST WINDOW IN LIVING ROOM PARTS REQUIRED LN Item Description Location Specification Size Options Gay 170 NEWMAR VINYL CASEMENT B3 SCREENS-REPLA 25,0625 X CEMENT-WINDO 55,125 WS Cause: Date Completed: Date Completed: Approved: Approved: Time: Service Signature: Service Signature:	Site Fax:			Lot#:	17	Phase:	
Home Phone(s): Cell Phone(s): Email(s): LINKED ORDER INFORMATION (D375521-1) Customer: N000582 ZANCOR BRAMPTON	RESIDENT	INFORMATION					
Cell Phone(s): Email(s): LINKED ORDER INFORMATION (D375521-1) Customer: N000582 ZANCOR BRAMPTON Lot #: 17 Models: 36-5 / OPT-58 / RR.UPG (WOB) (CB) Phase: SERVICE INSTRUCTIONS FOYER/HALL- TRIM-DAMAGED DOOR TRIM MIDDLE. JOHN BEDROOM #3- WINDOWS-WINDOW SCREEN BOWED BEDROOM RIGHT OF STAIRS JOHN MASTER ENSUITE BATH- TRIM-DAMAGED WINDOW MULLIN LEFT SIDE. LIVING ROOM- GENERAL- ADJUST WINDOW IN LIVING ROOM PARTS REQUIRED LIVING ROOM- GENERAL- ADJUST WINDOW IN LIVING ROOM PARTS REQUIRED LN Item Description: B3 SCREENS-REPLA 25.0625 X CEMENT-WINDO 55.125 WS Problem Description: CHARGEABLES Material \$ Labour \$ Labour \$ Labour \$ P.O.#: Cause: Date Completed: JULY JO JA Approved: John John John John John John John John	Home Owne	er Name:		Address:			
LINKED ORDER INFORMATION (D375521-1) Customer: N000582 ZANCOR BRAMPTON	Home Phon	e(s):		Work Pho	one(s):		
Customer: N000582 ZANCOR BRAMPTON	Cell Phone(s	s):		Email(s):			
Model: 36-5 / OPT.5B / RR.UPG (WOB) (CB) Phase: SERVICE INSTRUCTIONS FOYER/HALL- TRIM-DAMAGED DOOR TRIM MIDDLE. COMU BEDROOM #3- WINDOWS-WINDOW SCREEN BOWED BEDROOM RIGHT OF STAIRS COMU MASTER ENSUITE BATH- TRIM-DAMAGED WINDOW MULLIN LEFT SIDE. LIVING ROOM-GENERAL- ADJUST WINDOW IN LIVING ROOM PARTS REQUIRED LIN Item Description Location Specification Size Options Qty 170 NEWMAR VINYL CASEMENT B3 SCREENS-REPLA 25.0625 X CEMENT-WINDO 55.125 WS Problem Description: Warranty Warranty Material \$ Labour \$ P.O.#: Cause: Date Completed: Juy Ja Ja Approved: Time: Service Signature:	LINKED O	RDER INFORMATION (D37	5521-1)				
SERVICE INSTRUCTIONS FOYER/HALL- TRIM-DAMAGED DOOR TRIM MIDDLE. JOHN BEDROOM #3- WINDOWS-WINDOW SCREEN BOWED BEDROOM RIGHT OF STAIRS JOHN MASTER ENSUITE BATH- TRIM-DAMAGED WINDOW MULLIN LEFT SIDE. JOHN LIVING ROOM- GENERAL- ADJUST WINDOW IN LIVING ROOM PARTS REQUIRED LIN Item Description Location Specification Size Options Qty 170 NEWMAR VINYL CASEMENT B3 SCREENS-REPLA 25.0625 X CEMENT-WINDO 55.125 WS Problem Description: Warranty Material \$ Labour \$ Location Specification Size Options Qty 1 CHARGEABLES Material \$ Labour \$ P.O.#: Cause: Date Completed: John John John John John John John John	Customer:	N000582 ZANCOR BRAMPT	NC		Lot #: 1	17	
BEDROOM #3- WINDOWS-WINDOW SCREEN BOWED BEDROOM RIGHT OF STAIRS JOWN MASTER ENSUITE BATH- TRIM-DAMAGED WINDOW MULLIN LEFT SIDE. LIVING ROOM- GENERAL- ADJUST WINDOW IN LIVING ROOM PART'S REQUIRED LN Item Description Location Specification Size Options Qty 170 NEWMAR VINYL CASEMENT B3 SCREENS-REPLA 25.0625 X CEMENT-WINDO 55.125 WS Problem Description: Warranty Material \$ Labour \$ Material \$ Labour \$ P.O.#: Cause: Date Completed: July Ja Ja Approved: Time: Service Signature:	Model:	36-5 / OPT.5B / RR.UPG (WC)B) (CB)		Phase:		
BEDROOM #3- WINDOWS-WINDOW SCREEN BOWED BEDROOM RIGHT OF STAIRS OF COMMERCE AND ADDRESS OF COMMERCE AN	SERVICE	NSTRUCTIONS		٨			
MASTER ENSUITE BATH- TRIM-DAMAGED WINDOW MULLIN LEFT SIDE. LIVING ROOM- GENERAL- ADJUST WINDOW IN LIVING ROOM PARTS REQUIRED LN Item Description Location Specification Size Options Qty SCREENS-REPLA 25.0625 X CEMENT-WINDO 55.125 Problem Description: Warranty Material \$ Labour \$ Labour \$ P.O.#: Cause: Date Completed: July Ja Ja Approved: Time: Service Signature:	FOYER/HAL	L- TRIM-DAMAGED DOOR TE	RIM MIDDLE	dou			
MASTER ENSUITE BATH- TRIM-DAMAGED WINDOW MULLIN LEFT SIDE. LIVING ROOM- GENERAL- ADJUST WINDOW IN LIVING ROOM PARTS REQUIRED LN Item Description Location Specification Size Options Qty SCREENS-REPLA 25.0625 X CEMENT-WINDO 55.125 Problem Description: Warranty Material \$ Labour \$ Labour \$ P.O.#: Cause: Date Completed: July Ja Ja Approved: Time: Service Signature:					d.	nu I	
PARTS REQUIRED LIN Item Description Location Specification Size Options Qty 170 NEWMAR VINYL CASEMENT B3 SCREENS-REPLA 25.0625 X CEMENT-WINDO 55.125 WS Problem Description: CHARGEABLES Material \$ Labour \$ Labour \$ P.O.#: Cause: Date Completed: Date Completed: Specification Size Options Qty Options Qty Approved: Approved: Size Options Qty Approved: Approved: Size Options Qty Approved: Approved: Size Options Qty Approved: Approved: Service Signature:	BEDROOM	#3- WINDOWS-WINDOW SCR	EEN BOWE	D BEDROOM RIGHT	OF STAIRS	om	
PARTS REQUIRED LIN Item Description Location Specification Size Options Qty 170 NEWMAR VINYL CASEMENT B3 SCREENS-REPLA 25.0625 X CEMENT-WINDO 55.125 WS Problem Description: CHARGEABLES Material \$ Labour \$ Labour \$ P.O.#: Cause: Date Completed: Date Completed: Specification Size Options Qty Options Qty Approved: Approved: Size Options Qty Approved: Approved: Size Options Qty Approved: Approved: Size Options Qty Approved: Approved: Service Signature:	MASTER EN	NSUITE BATH- TRIM-DAMAGE	D WINDOW	MULLIN LEFT SIDE	dou		
PARTS REQUIRED LN Item Description Location Specification Size Options Qty 170 NEWMAR VINYL CASEMENT B3 SCREENS-REPLA 25.0625 X CEMENT-WINDO 55.125 WS Problem Description: CHARGEABLES Material \$ Labour \$ P.O.#: Cause: Date Completed: July Ja Ja Ja Approved: Service Signature:					110		
170 NEWMAR VINYL CASEMENT B3 SCREENS-REPLA 25.0625 X CEMENT-WINDO 55.125 WS Problem Description: Warranty	PARTS RE	QUIRED					
CEMENT-WINDO 55.125 WS Problem Description: Warranty CHARGEABLES Material \$ Labour \$ P.O.#: Cause: Date Completed: July 20-22 Approved: Final Service Signature: Service Signature:	LN Item Des	scription	Location	Specification	Size	Options	Qty
Problem Description: Warranty Material \$ Labour \$ P.O.#: Date Completed: JJJ JJ Approved: Time: Service Signature:	170 NEWM	IAR VINYL CASEMENT	B3				1
Problem Description: Warranty Material \$ Labour \$ Labour \$ P.O.#: Cause: Date Completed: Juy 20 20 Time: Service Signature:					55.125		
Warranty CHARGEABLES Material \$ Labour \$ P.O.#: Cause:				VVS			
Warranty CHARGEABLES Material \$ Labour \$ P.O.#: Cause:	Problem Des	scrintion*					
Material \$ Labour \$ Labour \$ P.O.#: Cause: Date Completed: Juy 20 22 Approved: Time: Service Signature:	T TODIONI BOX	5011200112					
Labour \$ P.O.#: Cause: Date Completed: Jug Ju Ju Approved: Time: Service Signature:	Warranty			CHAR	GEABLES		
P.O.#: Cause: Solution: Date Completed: July Ja Ja Approved:	Material \$			Material \$	1117		
Cause: Solution: Date Completed: July 20, 22 Time: Service Signature:	Labour \$		Labour \$	NIC			
Solution: Date Completed: July 20-22 Approved: Time: Service Signature:				P.O.#:			
Date Completed: July 20,77 Approved:	Cause:						
Date Completed: July 20,77 Approved:					10. 10.		
Date Completed: July 20,77 Approved:	0.1.0						
Time: Service Signature:	Solution:						
Time: Service Signature:							
Time: Service Signature:					0		
Time: Service Signature:	Date Com	pleted: Tild 20	21	Appr	oved:	>	
			0 0		A		
						1	
		Time:		Service Signa	ature:	J-0/	
		7				ZAHER	•



Phone: (905) 738-7010

Fax: (905) 738-5948

Work Order

Closing Date:	26May22								
Address: Location: Today's Date: Contact(s): Email:	Reserv 17May								
Company:	Newma	ar 🚶							
Attention: Telephone: Fax:		72-1233 72-6350							
Please Compl	ete the fol	llowing items:		<u> </u>	1	ê			
DAI	Туре	Issue		Appt. Date/Time	Notes				
147779	PDI	FOYER/HALL- TRIM~DAMAGED DOOR TRIM MIDDLE							
147797	PDI	BEDROOM #3- WINDOWS~WINDOW SCREEN BOWED BEDROOM RIGHT OF STAIRS							
147782	PDI	MASTER ENSUITE BATH- TRIM~DAMAGED WINDOW MULLIN LEFT SIDE							
Date Completed: 20 - 22			Homeowner Signature: X The Homeowner acknowledges and accepts all work has been completed in a workman like manner.						
Date Completed July 20 - 22			Trade &/or Service Tech.						
				Signature:					
			Print Na	ame:	Mey				

Please schedule your Service Department to complete work on the above Lot. Should no

appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

Failure to comply with this request within 10 business days will give Zancor Homes (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

Reserve Of Country Trails - Phase: 1 - Lot: 17

147779 - 1 - TRIM~DAMAGED DOOR TRIM MIDDLE



147797 - 1 - WINDOWS~WINDOW SCREEN BOWED BEDROOM RIGHT OF STAIRS



147782 - 1 - TRIM~DAMAGED WINDOW MULLIN LEFT SIDE

